

Product Change Notice

PCN#: EE-PCN24007

1/23/2024

CLASSIFICATION OF CHANGE:

Manufacturing process change.

DESCRIPTION OF CHANGE:

There has been a change to the fuse terminal manufacturing process.

REASON FOR CHANGE:

The fuse manufacturing process has been adjusted to improve the consistency of the fuse terminal height which will improve the fuse to PCB solderability.

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

There will be no effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices. Previous versions of this product are still acceptable for use and should not be returned.

PARTS FAMILIES AFFECTED:

Material #	Catalog Number
CC12M10A	CC12M10A
CC12M12A	CC12M12A
CC12M15A	CC12M15A

TIME SCHEDULE:

Start Shipment Date: Q4 2023

SAMPLE AVAILABILITY:

Available upon request

QUALIFICATION DATA:

Available upon request

ISSUED BY:

Global Product Manager: Elon Brown

CONTACT INFORMATION:

For questions or comments, please [Contact us](#)