









**4**

	$\varnothing C1$ mm	$\varnothing C2$ mm	$M_{max.}$ Nm
M12x1,5	3-5	5-8	5
M16x1,5	5-7,5	7,5-10,5	7
M20x1,5	8-10,5	10,5-15	12
M25x1,5	12,5-15,5	15,5-20,5	12
M32x1,5	17-20,5	20,5-25,5	15
M40x1,5	24-29	29-33	15
M50x1,5	31-37,5	37,5-42	30
M63x1,5	40-46	46-53	60





**5**

	$\varnothing E$ mm	$\varnothing C1$ mm	$\varnothing C2$ mm	$M_{max.}$ Nm
M12x1,5	3,5-5,5	3-5	5-8	5
M16x1,5	5,5-8	5-7,5	7,5-10,5	7
M20x1,5	8-11	8-10,5	10,5-15	12
M25x1,5	10-15	12,5-15,5	15,5-20,5	12
M32x1,5	13-20	17-20,5	20,5-25,5	15
M40x1,5	20-27	24-29	29-33	15
M50x1,5	26-34	31-37,5	37,5-42	30
M63x1,5	34-44	40-46	46-53	60

