

Product change notification (PCN)

Title / short description	AXL F BK S3 – 2701686, firmware 1.41
Affected article category	SPS and I/O systems
Change category	Function, Marking
Change number	CDR230106-AXL F BK S3 FW1.41-0
Reason for PCN/PDN Revision	

Purpose/objective of the change

Firmware optimization

Detailed description of the change

The following changes have been made for firmware 1.41:

- Removal of non-resettable error (connection loss): Sercos error code C30F4002
- The other technical properties, as described in the data sheets, remain unchanged

Identifying characteristics

Product revision (hardware and firmware status)

Start of Production (SOP)	-	Last Time Delivery (LTD)	-
Effective date (EOP)	2024-03-01	End of Service (EOSR)	-
End of Sales (EOS)	-		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|--|---|--|
| ☒ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☐ Product improvement with customer benefits | |
| ☐ Others | | |


Attachments

- Printing.jpg
- Material_list.csv
- PCN-CDR230106-AXL F BK S3 FW1.41-0_DE
- PCN-CDR230106-AXL F BK S3 FW1.41-0_EN

Material list

Item no.	Item Type	Hardware / Firmware		Item no.	Substitute item Type
		old	new		
2701686	AXL F BK S3	HW 05 / FW 1.40	HW 05 / FW 1.41		

Bedruckung alt
Printing old



Bedruckung alt
Printing new

