



Date: 01/30/2024

PCN: 901

PRODUCT CHANGE NOTICE

Dear Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following products. This change is part of our effort and commitment to continuous improvement of our products and processes.

Change Type

Software

Products Affected

Part Number	Description	Old Revision	New Revision
F33H002B01	TRACKER FOX3-4G-M1-FB-WW-4G CATM1/NB1 BANDS 2, 3, 4, 5, 8, 12, 13, 20-2G FB-GNSS-ACCELEROMETER, INT/EXT ANT-MINI SIM-2 X RS232-3 I/O-I2C-RTC-1 WIRE-MINI USB-AVL SOFTWARE BAT-01 1000 MAH LI-ION BATTERY	E11	F11
F33H007S	TRACKER FOX3-4G-M1-WW-4G CATM1/NB1 BANDS JAPAN VERSION-GNSS-ACCELEROMETER, INT/EXT ANT-MINI SIM-2 X RS232-3 I/O-I2C-RTC-1 WIRE-MINI USB-AVL SOFTWARE BAT-01 1000 MAH LI-ION BATTERY	B11	C11

Description and Extent of Change

Lantronix is pleased to announce the release of new and improved FOX3 series firmware version 3.20.0_rc14. The release includes new features and bug fixes including:

NEW FEATURES:

- Support for PercepXion, a new management portal
- Increased DNS timeout to 30 seconds

Bug fixes:

- Fixed timeout for TLS handshake
 - Fixed parsing MBEDTLS_SSL_TLS1_3_NEW_SESSION_TICKET state
- Refer to the release notes for a complete list of features and bug fixes.

For customers that would like to take advantage of the new capabilities of firmware version 3.20.0_rc14, the new firmware available for download from our website: <http://www.lantronix.com/support/downloads>.

Reason for Change

New Firmware

Effect of Change on Fit, Form, Function

Functional changes as noted on release notes.

Effective Date of Change

This change will go into effect for the listed products built from **February 18, 2023** onwards.

If you have any questions, please contact your sales representative or contact Lantronix Technical Support by submitting a ticket to: <https://ltrxdev.atlassian.net/wiki/spaces/LTRXTS/overview>