



*February 7, 2024*

## ***Product Advisory #1897***

### ***Part Numbers VL-EPU-4011(Harrier) and VL-EPU-4012 (Owl) Dual- and Quad-core processor boards***

This is a formal notification regarding products supplied by VersaLogic Corp. Our records indicate that your company has purchased one of these products.

Please read this notice thoroughly to determine what impact this change may have on you with regard to your currently owned product or future purchases from VersaLogic Corp.

#### ***Affected Products***

<b>Products</b>	<b>Description</b>	<b>Old Revision Level</b>	<b>New Revision Level</b>
VL-EPU-4011-EAP-02X-08	"Harrier" Dual-core processor board	2.00	2.01
VL-EPU-4011-EDP-08X-32	"Harrier" Quad-core processor board	2.00	2.01
VL-EPU-4012-02X-08	"Owl" Dual-core processor board	1.00	1.01
VL-EPU-4012-08X-32	"Owl" Quad-core processor board	1.00	1.01

#### ***Changes Made to Products***

The thermal interface material was changed to improve manufacturability.

#### ***Customer Impact***

None. The revised product will operate identically to the previous version.

#### ***Fielded Units***

Use as-is.

#### ***Future Shipments***

New revision EPU-4011 began shipping December 2023.

New revision EPU-4012 began shipping November 2023.

#### ***Additional Information***

For additional information or assistance related to this change, please contact VersaLogic Technical Support at [Support@VersaLogic.com](mailto:Support@VersaLogic.com) or call (503) 747-2261.