



May 1, 2024

Discontinuation of Specific Not Recommended for New Designs and Consult Factory Models

Dear Valued Phihong Customer:

Please be advised that effective immediately the below Not Recommended for New Designs, Consult Factory and/or Special Order (MOQ or BTO) models are discontinued. The recommended Phihong replacement models are indicated but please understand that there might not be an available Phihong replacement model for every case.

MODEL NUMER

PSM03E-050Q-3W-R

PSM03S-050Q-3-R

PSM03S-050Q-3W-R

PSAC60W-480-R

PSAC60M-180-R

PSAA20R-120L6-R

POE16R-1AFG6-R

POE29U-1AF-R

POE36D-1AT-R

POE576U-8AT-R

POE29W-560-R

ACCY125X-R

POE370U-ACCY01

POE370U-ACCY02

POE61U-560DG-R

PSAA18U-120L6-R

PSAA18U-240L6-R

RECOMMENDED REPLACEMENT MODEL

AQ03E-050AW-R (MOQ applies)

AQ03S-050A-R

AQ03S-050AW-R (MOQ applies)

PPL65W-480, AA65W-480 (MOQ applies)

PPL65U-180, AA65U-180A-R, PPL65M-180 (MOQ applies),

AA65M-180A-R (MOQ applies)

AA20R-120A-R

POE16R-1AFG6-2-R

POE576U-8BT-R (MOQ applies)

POEA30U-560E-R

POE60U-560E-R (MOQ applies)

PPL18U-120

PPL18U-240

Please do not hesitate to consult your Phihong contact if you should have any questions.

Sincerely,

Thomas Chin

Sr. Product Marketing Manager

Phihong USA Corp.