



Product Change Notification		Date
		April 19, 2024
Product	IX10/IX20/IX20W/IX30/IX40	

Description of change	New firmware version 24.3.28.88 available for all IX routers. This is a major production release. Digi recommends all customers update their IX products to firmware v24.3.28.88
-----------------------	--

Reason for Change	<p>New Firmware Version 24.3.28.88 provides:</p> <ul style="list-style-type: none"><li>• New Features</li><li>• Enhancements</li><li>• Bug Fixes</li><li>• Security Fixes</li></ul> <p>See Release Notes for more details.</p>
-------------------	--

Product Notice	<p>A new stable firmware version has been released for the IX, version 24.3.28.88. Use the link below to view the full list of changes, features, and fixes included in the new firmware.</p> <p><a href="#">IX Release Notes</a></p> <p><b><u>To take advantage of the new features, you must take action to update your device.</u></b> Refer to the instructions to update your firmware in the release notes above for more information.</p> <p>Any questions or concerns about the new firmware, or for assistance updating your device(s), please contact the <a href="#">Digi Support team</a></p>
----------------	---

Affected SKUs	IX10-00G4, IX10-00N4, IX10-00C6, IX15-00G4-XB2, IX15-00G4-XBP2, IX20-W0P4, IX20-00P4, IX20-W007, IX20-0007, IX20-W0G4, IX20-00G4, IX20-W0N4, IX20-00N4, IX20-0045, IX20-W0M1, IX20-00M1, IX30-00P7, IX30-00G4, IX30-00A4, IX40-04, IX40-05
---------------	--

Timing of Change	Effective Immediately
------------------	-----------------------