



Product Change Notification		Date April 19, 2024
Product	TX40/TX54/TX64	

Description of change	New firmware version 24.3.28.88 available for TX40/TX54/TX64 products. This is a major production release. Digi recommends all customers update their TX40/TX54/TX64 products to firmware v24.3.28.88
------------------------------	---

Reason for Change	New Firmware Version 24.3.28.88 provides: <ul style="list-style-type: none">• New Features• Enhancements• Bug Fixes• Security Fixes See Release Notes for more details.
--------------------------	--

Product Notice	<p>A new stable firmware version has been released for the Transportation cellular products, version 24.3.28.88. Use the link below to view the full list of changes, features, and fixes included in the new firmware.</p> <p>TX-seriesRelease Notes</p> <p><u>To take advantage of the new features, you must take action to update your device.</u> Refer to the instructions to update your firmware in the release notes above for more information.</p> <p>Any questions or concerns about the new firmware, or for assistance updating your device(s), please contact the Digi Support team</p>
-----------------------	---

Affected SKUs	TX54-A106, TX54-A112, TX54-A206, TX54-A246, TX54-A146, TX54-A152, TX54-A156, TX54-A256, TX64-A161, TX64-A161-PR, TX64-A121, TX64-A141, TX64-R210, TX64-R210-PR, TX40-A500, TX40-A400
----------------------	--

Timing of Change	Effective Immediately
-------------------------	-----------------------