

PRODUCT BULLETIN

CONFIDENTIAL – DO NOT DISTRIBUTE EXTERNALLY EXCEPT TO CUSTOMERS EXPLICITLY NOTED BELOW

DATE ISSUED:	27-May-2024	TRACKING NUMBER:	41114761
ISSUED BY:	IoT Solutions Product Management		
PRODUCTS AFFECTED:	EM9191		
SKUS AFFECTED:	1105108		
BULLETIN:	SKU firmware update		
URGENCY:	Normal		
EFFECTIVE DATE:	April 26, 2024		
FOR DISTRIBUTION TO:	All customers of SKU 1105108		

Summary

The SKU firmware is updated to the configuration shown below as of the effective date shown above.

Details of Change

The shipping SKU is being updated to SKU Rev D:

SKU Config->	SKU Rev 2	SKU Rev 5	
Carrier	Firmware	Firmware	Carrier PRI version
AT&T	03.10.07.00	03.10.07.00	030.059_002
Bell	03.10.07.00	03.14.10.01	030.045_000
Deutsche Telekom	Not loaded	03.10.07.00	030.048_000
Docomo	03.10.07.00	03.10.07.00	030.053_002
Generic	03.10.07.00	03.14.10.01	030.091_000
KDDI	03.10.07.00	03.10.07.00	030.035_001
Rogers	03.10.07.00	03.14.10.01	030.047_000
Softbank	03.10.07.00	03.10.07.00	030.043_000
Telus	Not loaded	03.14.10.00	030.079_000
Telstra	03.10.07.00	Not loaded	-
TMO US	03.10.07.00	03.14.10.01	030.083_000
Verizon	03.10.11.00	03.14.10.00	030.089_000

External marking:

The red arrows in the figures below show the change in the external label markings.
The factory serial number (FSN) is also indicated on the figure below. Digits 3, 4, and 5 can be used to correlate module SKU revision and module marking.

The following table summarizes the correlation between the SKU revision and external markings:

SKU Rev	Revision marking	FSN digits 3,4,5 (xxx)	Shipped
2	B	xxx < 403	Before Feb 2024
5	B	403 <= xxx < 415	Feb 2024 or later
5	D	xxx >=415	April 2024 or later

