



Product Change Notification / SYST-05QNAF314

Date:

06-Jun-2024

Product Category:

Ethernet Switches

PCN Type:

Document Change

Notification Subject:

LAN969x Silicon Errata and Data Sheet Clarification

Affected CPNs:

[SYST-05QNAF314_Affected_CPN_06062024.pdf](#)

[SYST-05QNAF314_Affected_CPN_06062024.csv](#)

Notification Text:

SYST-05QNAF314

Microchip has released a new Document for the LAN969x Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [LAN969x Silicon Errata and Data Sheet Clarification](#).

Notification Status: Final

Description of Change: Initial Release

Impacts to Data Sheet: None

Reason for Change: To improve productivity

Change Implementation Status: Complete

Date Document Changes Effective: 06 Jun 2024

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

LAN969x Silicon Errata and Data Sheet Clarification

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

LAN9694-V/3KW

LAN9694RED-V/3KW

LAN9694TSN-V/3KW

LAN9696-V/3KW

LAN9696RED-V/3KW

LAN9696TSN-V/3KW

LAN9698-V/3KW

LAN9698RED-V/3KW

LAN9698TSN-V/3KW