

MACOM

100 Chelmsford Street
Lowell, MA 01851
+1 978.656.2500

www.macom.com



Partners from RF to Light

Oct 30th, 2024

Digi-Key Corporation
701 Brooks Ave South
Thief River Falls, Minnesota 56701

ATTN: Quality/Purchasing Manager

PCN-01785

Subject: Adding additional inspection site.

Dear Valued Customer,

MACOM Technology Solutions has a goal of providing redundant manufacturing capability for increased surge capacity as well as an uninterrupted supply chain. In alignment with this goal, we are pleased to announce an additional inspection site for the parts listed in the next pages.

In addition to our current sites, we planned to inspect these parts at our long-standing Contract Manufacturer, Year 2000, Ho Chi Minh City, Vietnam. Year 2000 is a valued, high-quality manufacturing partner for many MACOM products.

In accordance with MACOM Technology Solutions' customer notification policy, you are receiving this notice because you have purchased one or more of the products listed in the previous two-year period.

Please contact your local sales representative if you have any specific questions.

Sincerely

Tom Galluccio
Director, Product Marketing
thomas.galluccio@macom.com

| | | |
|--|--------------------|---|
| PCN Number: PCN-01785 | | PCN Date: Oct 30 th , 2024 |
| Title: Adding additional inspection site. | | |
| Proposed 1st Ship Date: Jan 30 th , 2025 | | Estimated Sample Availability: Sample's availability based on the transfer progress of each part case by case |
| Change Type: | | |
| Assembly Site | Design | Electrical Specification |
| Test Site | Assembly Process | Mechanical Specification |
| Inspection Site X | Assembly Materials | Packing/Shipping/Labeling |
| PCN Details | | |
| Description of Change: | | |
| MACOM has identified a second source to inspect the affected parts. There is no change to the form, fit, materials, or performance of the device as a result of this change. | | |
| Reason for Change: | | |
| Increase the flexibility and continuity of supply. | | |
| Products Affected: | | |
| See next pages. | | |
| Anticipated impact on Fit, Form, Function: | | |
| Form, Fit and Function unaffected. | | |
| Changes to product identification resulting from this PCN: | | |
| None | | |

Appendix I
Affected part numbers

| No. | Part number | Part type |
|-----|--------------------|-----------|
| 1 | MADP-042408-130600 | Chip |
| 2 | MA4M1100 | Chip |
| 3 | MASW-011108-DIE | Chip |
| 4 | MADL-011052-14280W | Chip |
| 5 | MA4E2532M-1113 | Chip |
| 6 | MA4SPS302 | Chip |
| 7 | MAT10070 | Chip |
| 8 | MAT10000 | Chip |
| 9 | MASWSD0006 | PLASTIC |