

PCN Number:	20160608000	PCN Date:	06/10/2016
Title:	Datasheet for PGA450-Q1		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/> Assembly Site	<input type="checkbox"/> Design	<input type="checkbox"/> Wafer Bump Site	
<input type="checkbox"/> Assembly Process	<input checked="" type="checkbox"/> Data Sheet	<input type="checkbox"/> Wafer Bump Material	
<input type="checkbox"/> Assembly Materials	<input type="checkbox"/> Part number change	<input type="checkbox"/> Wafer Bump Process	
<input type="checkbox"/> Mechanical Specification	<input type="checkbox"/> Test Site	<input type="checkbox"/> Wafer Fab Site	
<input type="checkbox"/> Packing/Shipping/Labeling	<input type="checkbox"/> Test Process	<input type="checkbox"/> Wafer Fab Materials	
		<input type="checkbox"/> Wafer Fab Process	

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification.
The product datasheet(s) is updated as seen in the change revision history below:



PGA450-Q1

SLDS185D – MARCH 2012 – REVISED JUNE 2016

www.ti.com

Changes from Revision C (November 2015) to Revision D

Page

- Changed the bit numbers for the Byte #1 breakdown in the *SPI Protocol Transfer Widths* table 57
- Added the byte #4 data for the external RAM read in the *SPI Protocol Transfer Widths* table 57
- Changed the address of the OTP program code area from 0x1000 to 0x0000 in the *PGA450 Memory Map* figure 70
- Changed the SAT_SEL0 value for 600 mV from 0 to 1 in the *SAT_SELx Bit Configuration* table 96

Device Family	Change From:	Change To:
PGA450-Q1	SLDS185C	SLDS185D

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/pga450-q1>

Reason for Change:

To more accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

PGA450TPWRQ1

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com