

Product/Process Change Notifications



PCN - 19 050

Amphenol Information Communication and Commercial Products Group
www.amphenol-icc.com

Release Date: June 28 2019

| | | | |
|------------------------------------|--|----------------------------|--|
| Product Name: | Powerblade+ cable assembling | | |
| | See attached | | |
| Product Manager: | Alfred Wang | | |
| Subject: | Notification of Change with Immediate Effectivity | | |
| Distribution: | Affected Customers | | |
| Type of Change: | Design Change | | |
| Change Description: | 1. Change Low power pin structure, detail see attached. 2. Change the structure of Housing | | |
| Reason for Change: | The change is to increase the retention force between terminal and housing, the change will not impact electrical performance, nor customer application. This is a minor change for improvement. | | |
| Affected Parts: | See Affected parts.xls file | | |
| Effective Date of Change: | Jul/28/2019 | | |
| Last Time Buy Date: | na | | |
| Earliest Disty Return Date: | na | | |
| Last Time Shipment Date | na | | |
| Datasheet Attached? | Yes | see Sheet "attached Files" | |
| Qual/Test Data Attached? | Yes | see Sheet "attached Files" | |
| Samples Availability Date: | June 28,2019 | | |
| Available Alternatives? | N/A | | |
| Questions? | Contact your local AICC Representative, or Product Manager | | |
| | Alfred Wang /Product Manager | | |
| | +86 76988669320 / Alfred.wang@fci.com | | |

Note:

Customers should contact Product Manager (or their local AICC Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

| PCN Reference | MPN |
|---------------|--------------------|
| PCN19050 | 10147865-001LF |
| PCN19050 | 10129500-1UB0007LF |
| PCN19050 | 10129500-3ND0022LF |
| PCN19050 | 10129500-3UB0016LF |
| PCN19050 | 10129500-4UC0031LF |
| PCN19050 | 10129500-4WB0024LF |
| PCN19050 | 10129500-4WB0025LF |
| PCN19050 | 10129500-4CB0232LF |
| PCN19050 | 10129500-4CD0249LF |
| PCN19050 | 10129500-4ND0099LF |
| PCN19050 | 10129500-4ND0163LF |
| PCN19050 | 10129500-4UB0143LF |
| PCN19050 | 10129500-4VA0224LF |
| PCN19050 | 10129500-4VB0208LF |
| PCN19050 | 10129500-4VB0209LF |
| PCN19050 | 10129500-4VB0218LF |
| PCN19050 | 10129500-4VB0219LF |
| PCN19050 | 10129500-4VB0220LF |
| PCN19050 | 10129500-4VB0227LF |
| PCN19050 | 10129500-4WB0068LF |
| PCN19050 | 10129500-4WB0137LF |
| PCN19050 | 10129500-4WB0267LF |
| PCN19050 | 10129500-6CA0235LF |
| PCN19050 | 10129500-6CB0263LF |
| PCN19050 | 10129500-6CB0264LF |
| PCN19050 | 10129500-6HA0126LF |
| PCN19050 | 10129500-6HA0158LF |
| PCN19050 | 10129500-6MA0127LF |
| PCN19050 | 10129500-6SB0207LF |
| PCN19050 | 10129500-6UB0210LF |
| PCN19050 | 10129500-6UB0211LF |
| PCN19050 | 10129500-6VB0150LF |
| PCN19050 | 10129500-6VB0151LF |
| PCN19050 | 10129500-MND0215LF |
| PCN19050 | 10130664-3C0053LF |
| PCN19050 | 10130664-3C0072LF |
| PCN19050 | 10130664-3C0111LF |
| PCN19050 | 10130664-3C0112LF |
| PCN19050 | 10135690-091102LF |
| PCN19050 | 10129500-4UA0008LF |