



20050 SW 112th Ave. Tualatin, Oregon 97062  
phone: 800.275.4899 fax: 503.612.2383  
www.cui.com

## Product Discontinuation

6/7/2022

CUI regrets to announce plans to obsolete the following parts effective immediately. We are not able to accept last time buy (LTB) orders.

| Obsolete Part Number | Recommended Alternatives |
|----------------------|--------------------------|
| PCM-400-D0512-CF     | none                     |
| PCM-400-D0512-CFS    | none                     |
| PCM-400-D0512-CNF    | none                     |
| PCM-400-D0512-U      | none                     |
| PCM-400-D0524-CF     | none                     |
| PCM-400-D0524-CFS    | none                     |
| PCM-400-D0524-CNF    | none                     |
| PCM-400-D0524-U      | none                     |
| PF-400-D524-CFS-C1   | none                     |
| VF-D250-D1224A-CF-3  | none                     |
| VF-D250-D312A        | none                     |
| VF-D250-D512A        | none                     |
| VF-D250-D512A-CF     | none                     |
| VF-D250-D524A        | none                     |
| VF-D250-D524A-CF     | none                     |
| VF-D320-D512A        | none                     |
| VF-D320-D512A-1      | none                     |
| VF-D320-D512A-CF     | none                     |
| VF-D320-D512A-CFS    | none                     |
| VF-D320-D512A-CFS-1  | none                     |
| VF-D320-D512A-GE     | none                     |
| VF-D320-D524A        | none                     |
| VF-D320-D524A-1      | none                     |
| VF-D320-D524A-CFS    | none                     |
| VF-D320-D524A-CFS-1  | none                     |
| VF-D320-D548A-1      | none                     |
| VF-D320-D548A-CFS-1  | none                     |
| VF-S250-05A          | VGS-200D-5               |
| VF-S250-05A-CF       | VGS-200D-5               |
| VF-S250-05A-CF-2L    | VGS-200D-5               |
| VF-S250-09A          | none                     |
| VF-S320-05A          | VGS-320D-5               |



20050 SW 112th Ave. Tualatin, Oregon 97062  
phone: 800.275.4899 fax: 503.612.2383  
[www.cui.com](http://www.cui.com)

|                   |            |
|-------------------|------------|
| VF-S320-05A-1     | VGS-320D-5 |
| VF-S320-05A-CFS   | VGS-320D-5 |
| VF-S320-05A-CFS-1 | VGS-320D-5 |
| VF-S320-09A       | none       |
| VF-S320-09A-1     | none       |
| VF-S320-09A-CF    | none       |
| VF-S320-09A-CFS   | none       |
| VF-S320-09A-CFS-1 | none       |
| VMS-300-D0512     | none       |
| VMS-300-D0512-CF  | none       |
| VMS-300-D0512-CFS | none       |
| VUF-D400-D524     | none       |
| VUFM-D400-312R    | none       |
| VUFM-D400-D324    | none       |
| VUFM-D400-D512    | none       |
| VUFM-D400-D524    | none       |
| VUF-S400-05R      | none       |
| VUM-D400-D312     | none       |
| VUM-D400-D512     | none       |
| VUM-D400-D524     | none       |

If you have any questions concerning the discontinuation notice,  
please contact your local CUI Representative.