

## 1 Products affected

| Product hierarchy no. * |     |     |            | Part no.           | SBU | Product Type | Customer part no. |
|-------------------------|-----|-----|------------|--------------------|-----|--------------|-------------------|
| SBU                     | PG  | PUG | Type       |                    |     |              |                   |
| 02                      | 007 | 012 | 0000002051 | See appendix below |     | 6600-5       |                   |

\*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

## 2 Type of change

- Change of label
- Change of configuration code

## 1 Detailed description of change

| Current label                                                 | New label                                                 |
|---------------------------------------------------------------|-----------------------------------------------------------|
| <p>Current label configuration code: 6600-XXXX-XXXX-XX XX</p> | <p>New label configuration code: 6600-XXXX-XXXX-XX X0</p> |

- Change of Configuration Code and therefore change on label

## 2 Reason of change

- Added digit to the Configuration Code for enlargement of product range in the future.

## 3 Release date

The change takes effect in ww 17/2023 (Date code 2317 or higher on label).  
Parts on stock will be used upon depletion.

## 4 Impact of change and recommended action

- ☐ Form
- ☐ Fit
- ☐ Function
- ☐ Manufacturing
- ☒ Label New Configuration Code on label
- ☐ Packaging

| Product Change Notification |               |              |             |              | PCN 6600-5 Change of Configuration Code |        |             |
|-----------------------------|---------------|--------------|-------------|--------------|-----------------------------------------|--------|-------------|
| owner                       | creation date | release date | released by | change order | rev                                     | page   | D10-072-579 |
| sariogar                    | 03.04.2023    | 12.04.2023   | muehlema    | 2025706      | A                                       | 1 of 2 |             |

## 5 Reference Documents

| Kind of document | Document Title                    |
|------------------|-----------------------------------|
| Data Sheet       | <a href="#">Data Sheet 6600-5</a> |

## 6 Appendix

| List of part numbers affected for type 6600-5 |           |           |           |           |
|-----------------------------------------------|-----------|-----------|-----------|-----------|
| 3-100-403                                     | 3-100-404 | 3-100-405 | 3-100-406 | 3-101-685 |
| 3-101-686                                     | 3-101-687 | 3-101-689 | 3-103-271 | 3-103-282 |
| 3-103-283                                     | 3-103-284 | 3-103-285 | 3-108-087 | 3-108-088 |
| 3-108-089                                     | 3-108-090 | 3-108-091 | 3-110-957 | 3-120-511 |
| 3-127-267                                     | 3-137-773 | 3-137-774 |           |           |

| Product Change Notification |               |              |             |              | PCN 6600-5 Change of Configuration Code |        |             |
|-----------------------------|---------------|--------------|-------------|--------------|-----------------------------------------|--------|-------------|
| owner                       | creation date | release date | released by | change order | rev                                     | page   | D10-072-579 |
| sariogar                    | 03.04.2023    | 12.04.2023   | muehlema    | 2025706      | A                                       | 2 of 2 |             |