

Product Change Notice

PCN#: EE-PCN23008

4/18/2023

CLASSIFICATION OF CHANGE:

Plating appearance change

DESCRIPTION OF CHANGE:

Fuse clip 1A5018-07 silver plating color changed in new manufacturing line

REASON FOR CHANGE:

Add new manufacturing line to enlarge product capacity

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

Fuse clip 1A5018-07 is adding new product line, there is no effect on the quality, reliability, or performance. The new manufacture line produced fuse clip is bright silver plating without material change. The plating appearance changed from matt silver plating to bright silver plating shows as below



Matt Silver Plating



Bright Silver Plating

PARTS FAMILIES AFFECTED

BK-1A5018-07

TIME SCHEDULE:

Effective immediately

ISSUED BY:

Roald Bai

Product Manager – Circuit Protection

CONTACT INFORMATION:

For questions or comments, please [Contact us](#)