

PRODUCT CHANGE NOTICE

PCN Form (D4-E000-73)

PCN/EOL#22-061

NOTIFICATION DATE: August 22, 2022

MODELS AFFECTED:

| | | | | | | |
|---------------|----------|-----------|-----------|-----------|-----------|---------|
| BP2C+ | BP2U1+ | BP4C-5 | SP-2C1-3+ | SP-2U+ | SP-2W1+ | WP4A-2+ |
| BP2C+ REV Z9A | BP4C+ | SP-2C+ | SP-2C-2+ | SP-2U1+ | SP-2W1-1+ | WP4A-3+ |
| BP2C= | BP4C1+ | SP-2C-1+ | SP-2L+ | SP-2U2+ | SP-2W-2 | |
| BP2C1+ | BP4C1-1+ | SP-2C1+ | SP-2L-1+ | SP-2U2-1+ | SP-2W-2+ | |
| BP2C-5 | BP4C1-2+ | SP-2C1-1+ | SP-2L-2+ | SP-2W+ | WP4A+ | |
| BP2U+ | BP4C1-3+ | SP-2C1-2+ | SP-2L-3+ | SP-2W= | WP4A-1 | |

Including evaluation boards (TB's) for the above models

EXTENT OF CHANGE:

Discontinuation of listed products

EFFECT OF CHANGE:

Obsolescence of supplied die

REASON FOR CHANGE:

End of life notification received from supplier of critical internal components

EFFECTIVE DATE OF CHANGE:

Immediate, Last Time Buy availability is based on existing inventory.
Contact your Account Manager or sales@minicircuits.com for availability.

ATTACHMENTS:

N/A

QUESTIONS?

PLEASE CONTACT US.

AS9100 ISO9001 ISO14001 Certified to QMS and EMS