

Product Change Notice

Issue Date: 22-April-2022

Change Description:

Qualify new I²C (2-wire) Serial EEPROM

Parts Affected:

HFBR-57E5APZ

Description and Extent of Change:

Current situation:

- Affected parts are using I²C (2-wire) Serial EEPROM from a specific vendor with supply issues.

Change:

- Introduce I²C (2-wire) Serial EEPROM for production from 2 other suppliers (the microcontroller IC remains unchanged).

Reasons for Change:

- Long lead time for current I²C EEPROM due to supply issues of the current supplier
- Qualify new I²C (2-wire) Serial EEPROM suppliers to prevent production line stop and improve security of supply

Effective Date of Change:

Product shipments which may contain changed material may begin on or after **4 Oct 2022, (WW2241)**, but the initiation of the change may be spread over approximately 6 months. Timing of shipment of the changed part will vary by part number depending on qualification completion, customer demand, and inventory levels. Timing of shipment of the changed part will vary by part number depending on qualification completion, customer demand, and inventory levels.

Qualification Data:

Qualification samples for HFBR-57E5APZ will be available 4 July 2022.

Other affected parts samples need to be requested.