

Product Name:	HPL 599 - MICROSPACE		
	MICRO SPACE CABLE ASSY		
Product Manager:	Dorian MOYNE		
Subject:	Notification of Planned Change		
Distribution:	Affected customers		
Type of Change:	Process Change		
Change Description:	Crimp to wire terminals supplied from Amphenol FCI Besancon site will be localised at Amphenol Nantong site to integrate the production process of Microspace Cable harness business from Amphenol FCI Nantong.		
Reason for Change:	To minimize the supply chain risk and increase our output by having a tool duplicated and improve our service level, output and reactivity.		
Affected Parts:	See Affected Parts.xls file		
Effective Date of Change:	November,01 2023		
Last Time Buy Date:			
Earliest Disty Return Date:			
Last Time Shipment Date			
Datasheet Attached?	Yes		
Qual/Test Data Attached?	Yes		
Samples Availability Date:	10 May ,2023		
Available Alternatives?			
Questions?	Contact your local ACS Representative, or Product Manager		
	Dorian MOYNE / Product Manager		
	dorian.moyne@amphenol-fci.com / peng-fei.gu@fci.com		

Note:

Customers should contact Product Line Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

PCN Reference	MPN	Change	Effective Date
PCN23042	10155213-N0017YYLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10155213-N0020YYLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10155387-N0007YYLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10155387-N0008YYLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10155387-N0013YYLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10155387-N0019YYLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10155387-N0090YYLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10156368-P0014YYLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10156368-P0018YYLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10158882-P0030YYLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10162165-P0046YGLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10162165-P0046YYLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10162175-P0010YGLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10162175-P0010YYLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10162176-P0015YGLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10162176-P0015YHLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10162176-P0015YYLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10162177-P0015YALF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10162177-P0015YGLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10162177-P0015YYLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10162767-P0030YYLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10162820-N0030YYLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10163579-N0000ATLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10164131-N0000ATLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10168362-N0000ATLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10169367-001LF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10163579-N0021YYLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10163579-N0233YYLF	PROCESS CHANGE	NOVEMBER 1 , 2023
PCN23042	10169412-Z0100YYLF	PROCESS CHANGE	NOVEMBER 1 , 2023