

Product Change Notification

TE Connectivity

Product Change Notification: PCN-23-174011 PCN Date: 03-MAY-23

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

DIN 2-4POS. 2.5MM SOCKET HOUSING, DIN 5-7POS. 1.5MM SOCKET HOUSING

Description of Changes

The Industrial and Commercial Transportation business unit of TE Connectivity is transferring two production assembly lines that produce the part number(s) stated below from TE Connectivity Plant located in Esztergom, Hungary to TE Connectivity Plant in Tangier, Morocco. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. A TE-internal release test based on the relevant part specifications will be executed before delivery. These PNs are TE proprietary designs, therefore considered catalog/general market products. TE reserves the right to move tool back to prior location/supplier based on business need. PPAP and/or sample requests must be submitted within 14 days of PCN submission via ict-ppap-request@te.com or ePPAP system. Submission will not occur without request. If PPAP requested, disposition response is required within 14 days of submit date or it will be considered approved.

Reason for Changes:

Dear Customer, we hereby inform you of this transfer. The relocation of the assembly lines to Tangier, Morocco is to increase the plant utilization with the manufacturing of the DIN Socket assembly connector products at this location. IMPORTANT: The current and previous revisions of these parts can be used interchangeably in the field. The change(s) are being phased in gradually and previous revision can remain stocked until use. Shipments of both configurations may be mixed.

PCN Attributes:				
Product Category:	Kind of Change:			
Connector Housings	Location Change			
Change Feature:	Potential Customer Impact:			
No Feature Change	Localization			
Remarks:				

Estimated Dates:		
Last Order Date (Obsolete Parts Only):	First Ship Date of Changed Items (Changed Parts Only):	
	26-JUN-2023	
Last Ship Date of Changed Items (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):	
	30-OCT-2024	
Effectivity Date:	Date of First Samples:	

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>1-1719434-2</u>	NO						
<u>1-967325-1</u>	NO			"CB2703-000", "AMPS-1- 0967325-1", "820A-36908"			
1-967325-2	NO						
1-967325-3	NO						
<u>2-967325-1</u>	NO						
<u>2-967650-1</u>	NO						
<u>3-967325-3</u>	NO						
3-967650-1	NO						
<u>4-1719434-1</u>	NO						
<u>967650-1</u>	NO						
967650-2	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>4-1719434-</u> <u>1</u>	NO						
<u>967650-1</u>	NO						

Part Number(s) being Modified:

	Part ımber	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>4-17</u> <u>1</u>	19434-	NO						
9676	550-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>1-</u> 1719434-2	NO						
<u>1-967325-</u> <u>1</u>	NO			"CB2703-000", "AMPS-1- 0967325-1", "820A-36908"			
<u>1-967325-</u> <u>2</u>	NO						
<u>1-967325-</u> <u>3</u>	NO						
<u>2-967325-</u> <u>1</u>	NO						
<u>2-967650-</u> <u>1</u>	NO						
3-967325- <u>3</u>	NO						
<u>3-967650-</u> <u>1</u>	NO						
<u>967650-1</u>	NO						
967650-2	NO						