

To: Littelfuse Sales, Sales Support & Valued Customers

From: Littelfuse Product Management – Industrial Business Unit



Subject: SPXV, SPXV_CN, SPXI & SPXI_CN series label description change



Document Number: LFPCN_PG0155



Date: 10th April 2023



Dear Valued customer:



With regards to the above reference, Littelfuse would like to inform you that we have implemented and will be implementing a product label change to SPXV, SPXV_CN, SPXI & SPXI_CN Series fuses as per dates of implementation mentioned in below table. In this label format change, we have replaced UL certification mark with cULus certification mark as those products are compliant with CSA C22.2 No. 248.19 in addition to existing UL Compliance UL248-19 standard. There is no change to fit, form or function of the actual product.



Part number	SPXI / SPXI-B (1-20A) Series	
Change Description	Before	After
Label on fuse body		
Date of implementation	8 th June 2023	



Part number	SPXI-M / SPXI-BM (25-32A) Series	
Change Description	Before	After
Label on fuse body		
Date of implementation	30 th March 2023	



Part number	SPXV / SPXV-S (1-20A) Series	
Change Description	Before	After
Label on fuse body		
Date of implementation	18 th May 2023	



Part number	SPXV / SPXV-S (25-30A) Series	
Change Description	Before	After
Label on fuse body		
Date of implementation	8 th June 2023	

Part number	SPXV-M (25-32A) Series	
Change Description	Before	After
Label on fuse body		
Date of implementation	20 th April 2023	

Part number	SPXI_CN (1-20A) Series	
Change Description	Before	After
Label on fuse body		
Date of implementation	31 st March 2023	

Part number	SPXI-M_CN / SPXI-BM_CN (25-32A) Series	
Change Description	Before	After
Label on fuse body		
Date of implementation	31 st March 2023	

Part number	SPXV_CN (1-20A) Series	
Change Description	Before	After
Label on fuse body		
Date of implementation	31 st March 2023	

Part number	SPXV-M_CN (25-30A) Series	
Change Description	Before	After
Label on fuse body		
Date of implementation	31 st March 2023	

Part numbers affected:

PART NO.	PART NO.	PART NO.	PART NO.	PART NO.	PART NO.
SPXI001.T	SPXI001.TXB	SPXV001.T	SPXV001.TXS	SPXI001.TXCN	SPXV001.TXCN
SPXI001.L	SPXI001.LXB	SPXV001.L	SPXV001.LXS	SPXI001.LXCN	SPXV001.LXCN
SPXI002.T	SPXI002.TXB	SPXV002.T	SPXV002.TXS	SPXI002.TXCN	SPXV002.TXCN
SPXI002.L	SPXI002.LXB	SPXV002.L	SPXV002.LXS	SPXI002.LXCN	SPXV002.LXCN
SPXI2.25T	SPXI2.25TXB	SPXV2.25T	SPXV2.25TXS	SPXI2.25TXCN	SPXV2.25TXCN
SPXI2.25L	SPXI2.25LXB	SPXV2.25L	SPXV2.25LXS	SPXI2.25LXCN	SPXV2.25LXCN
SPXI02.5T	SPXI003.TXB	SPXV02.5T	SPXV02.5TXS	SPXI02.5TXCN	SPXV02.5TXCN
SPXI02.5L	SPXI003.LXB	SPXV02.5L	SPXV02.5LXS	SPXI02.5LXCN	SPXV02.5LXCN
SPXI003.T	SPXI03.5TXB	SPXV003.T	SPXV003.TXS	SPXI003.TXCN	SPXV003.TXCN
SPXI003.L	SPXI03.5LXB	SPXV003.L	SPXV003.LXS	SPXI003.LXCN	SPXV003.LXCN
SPXI03.5T	SPXI004.TXB	SPXV03.5T	SPXV03.5TXS	SPXI03.5TXCN	SPXV03.5TXCN
SPXI03.5L	SPXI004.LXB	SPXV03.5L	SPXV03.5LXS	SPXI03.5LXCN	SPXV03.5LXCN
SPXI004.T	SPXI04.5TXB	SPXV004.T	SPXV004.TXS	SPXI004.TXCN	SPXV004.TXCN
SPXI004.L	SPXI04.5LXB	SPXV004.L	SPXV004.LXS	SPXI004.LXCN	SPXV004.LXCN
SPXI04.5T	SPXI005.TXB	SPXV04.5T	SPXV005.TXS	SPXI04.5TXCN	SPXV04.5TXCN
SPXI04.5L	SPXI005.LXB	SPXV04.5L	SPXV005.LXS	SPXI04.5LXCN	SPXV04.5LXCN
SPXI005.T	SPXI006.TXB	SPXV005.T	SPXV006.TXS	SPXI005.TXCN	SPXV005.TXCN
SPXI005.L	SPXI006.LXB	SPXV005.L	SPXV006.LXS	SPXI005.LXCN	SPXV005.LXCN
SPXI006.T	SPXI008.TXB	SPXV006.T	SPXV008.TXS	SPXI006.TXCN	SPXV006.TXCN
SPXI006.L	SPXI008.LXB	SPXV006.L	SPXV008.LXS	SPXI006.LXCN	SPXV006.LXCN
SPXI008.T	SPXI010.TXB	SPXV008.T	SPXV010.TXS	SPXI008.TXCN	SPXV008.TXCN
SPXI008.L	SPXI010.LXB	SPXV008.L	SPXV010.LXS	SPXI008.LXCN	SPXV008.LXCN
SPXI010.T	SPXI012.TXB	SPXV010.T	SPXV012.TXS	SPXI010.TXCN	SPXV010.TXCN
SPXI010.L	SPXI012.LXB	SPXV010.L	SPXV012.LXS	SPXI010.LXCN	SPXV010.LXCN
SPXI012.T	SPXI015.TXB	SPXV012.T	SPXV015.TXS	SPXI012.TXCN	SPXV012.TXCN
SPXI012.L	SPXI015.LXB	SPXV012.L	SPXV015.LXS	SPXI012.LXCN	SPXV012.LXCN
SPXI015.T	SPXI016.TXB	SPXV015.T	SPXV016.TXS	SPXI015.TXCN	SPXV015.TXCN
SPXI015.L	SPXI016.LXB	SPXV015.L	SPXV016.LXS	SPXI015.LXCN	SPXV015.LXCN
SPXI016.T	SPXI020.TXB	SPXV016.T	SPXV020.TXS	SPXI016.TXCN	SPXV016.TXCN
SPXI016.L	SPXI020.LXB	SPXV016.L	SPXV020.LXS	SPXI016.LXCN	SPXV016.LXCN
SPXI020.T	SPXI025.TXBM	SPXV020.T		SPXI020.TXCN	SPXV020.TXCN
SPXI020.L	SPXI025.LXBM	SPXV020.L		SPXI020.LXCN	SPXV020.LXCN
SPXI025.T	SPXI030.TXBM	SPXV025.TXM		SPXI025.TXMCN	SPXV025.TXMCN
SPXI025.L	SPXI030.LXBM	SPXV025.LXM		SPXI025.LXMCN	SPXV025.LXMCN
SPXI025.TXM	SPXI032.TXBM	SPXV030.TXM		SPXI030.TXMCN	SPXV030.TXMCN
SPXI025.LXM	SPXI032.LXBM	SPXV030.LXM		SPXI030.LXMCN	SPXV030.LXMCN
SPXI030.T		SPXV032.TXM		SPXI032.TXMCN	SPXV032.TXMCN
SPXI030.L		SPXV032.LXM		SPXI032.LXMCN	SPXV032.LXMCN
SPXI030.TXM				SPXI025.TXBMCN	
SPXI030.LXM				SPXI025.LXBMCN	
SPXI032.TXM				SPXI030.TXBMCN	
SPXI032.LXM				SPXI030.LXBMCN	
				SPXI032.TXBMCN	
				SPXI032.LXBMCN	

If you have any questions, or need additional information please contact your Littelfuse representative.

Thank you for your continued business.

Sincerely,

Prashant Kulkarni

Associate Product Manager

Industrial Business Unit

Littelfuse, Inc.
