

PRODUCT CHANGE NOTIFICATION

Product Category VENTURES - NI **20230424-1**

Product Group PANDUIT VENTURES

ISSUE DATE: 24-Apr-23

IMPACTED REGIONS: ☒ NA ☒ EMEA ☒ LATAM ☒ AP

REASON FOR CHANGE: ☒ DISCONTINUATION
☐ OTHER

DESCRIPTION OF CHANGE: (Required)

Parts will be discontinued. Thank you for your ongoing support.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2023	7	24

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type
-------------------------	--------------------

FML15RAN	No Replacement
FML25RAN	No Replacement
FML45RAN	No Replacement
FML65RAN	No Replacement
FMLC5RAN	No Replacement
FML16RAN	No Replacement
FML26RAN	No Replacement
FML46RAN	No Replacement
FML66RAN	No Replacement
FMLC6RAN	No Replacement