1 Products affected


Product hierarchy no. *			chy no. *	Part no.	SBU	Product Type	Customer part no.
SBU	PG	PUG	Туре				
02	007	021	0000002432	6160.0003	Connectors	2563	n/a

^{*}SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

2 Type of change

Change of product design

3 Detailed description of change



 Retaining bracket is added as mandatory component. Before it was an optional accessory with part number 4700.0023.

4 Reason of change

Better fit and hold for PCB mount

5 Release date

The change takes effect in ww 38/2023 (Date code 2338 or higher on label). Parts on stock will be used upon depletion.

6 Impact of change and recommended action

\boxtimes	Form	Additional retaining bracket
\boxtimes	Fit	Verify the PCB drilling diagram and adjust your production process accordingly

☐ Function

Manufacturing

Product Change Notification					PCN	PCN 2563 Adding Retaining Braket		
owner	creation date	release date	released by	change order	rev	page	D40 074 566	
wiedersa	15.06.2023	15.06.2023	muehlema		В	1 of 2	D10-074-566	





Label
Packaging

7 Reference Documents

Kind of document	Document Title
Data Sheet 2563	

Product Change Notification					PCN 2563 Adding Retaining Braket		
owner	creation date	release date	released by	change order	rev	page	D40 074 F66
wiedersa	15.06.2023	15.06.2023	muehlema		В	2 of 2	D10-074-566