

Final Product Change Notification

202305020F01 : PTN36001HX/PTN36241GHX ATK to UTL Transfer

Note: This notice is NXP Company Proprietary.

Issue Date: Jun 23, 2023 Effective date:Sep 21, 2023

Here is your personalized notification about a NXP general announcement.

For detailed information we invite you to view this notification online

Management summary

Changing of PTN36001HX/PTN36241GHX assembly site from ATK to UTL due to ATK capacity shortage.

Change Category

[]Wafer Fab Process	[]Assembly Process	[]Product Marking	[]Test Process	[]Design
[]Wafer Fab Materials	[X]Assembly Materials	[]Mechanical Specification	[]Test Equipment	[]Errata
[]Wafer Fab Location	[X]Assembly Location	[X]Packing/Shipping/Labeling	[X]Test Location	[]Electrical spec./Test coverage
[]Firmware	[]Other			

PCN Overview

Description

- 1. Assembly, Test, Packing site of PTN36001HX/PTN36241GHX will change from ATK to UTL;
- 2. Bill of material of PTN36001HX/PTN36241GHX will change to current standards;
- 3. Packing/Labeling will change to current standards;

Pls. refer to attached PCN report for more details.

Reason

Changing of PTN36001HX/PTN36241GHX assembly site from ATK to UTL due to ATK capacity shortage.

Identification of Affected Products

Top Side Marking

Product Availability

Sample Information

Samples are available upon request

Production

Planned first shipmentSep 29, 2023

Anticipated Impact on Form, Fit, Function, Reliability or Quality

No Impact on form, fit, function, reliability or quality

Data Sheet Revision

No impact to existing datasheet

Disposition of Old Products

Existing inventory will be shipped until depleted

Additional information

Self qualification:view online

Timing and Logistics

In compliance with JEDEC J-STD-046, your acknowledgement of this change is expected by Jul 23, 2023.

Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

Name Beiping Zhang

Position Quality Engineer

e-mail

address beiping.zhang_1@nxp.com

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards. Customer Focus, Passion to Win.

NXP Quality Management Team.

About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

NXP Semiconductors

High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006-2023 NXP Semiconductors. All rights reserved.

Orderable Part Number#12NCProduct TypeProduct DescriptionPackage OutlinePackage DescriptionProduct StatusCustomer Specific IndicatorProduct LinePTN36241GHXZ935305821515PTN36021HXZ2 channel Superspeed USB 3 redriver(X2)FCQFN12SOT1408-1RFSNoBLG6PTN36001HXZ93530582151PTN36001HX2 channel Superspeed USB 3 redriver(X2)FCQFN12SOT1408-1RFSNoBLG6