



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001094I

DATE: 17-Jul-2023

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX1408EAI+	N/A	17-Jul-2023	17-Jul-2023	Part can no longer be manufactured
Discontinuance	MAX1408EAI+T	N/A	17-Jul-2023	17-Jul-2023	Part can no longer be manufactured
Discontinuance	MAX14585EVB+	N/A	17-Jul-2023	17-Jul-2023	Part can no longer be manufactured
Discontinuance	MAX14585EVB+T	N/A	17-Jul-2023	17-Jul-2023	Part can no longer be manufactured
Discontinuance	MAX20463AGTCA/V+T	MAX20463AGTCB/V+T	17-Jul-2023	17-Jul-2023	Part can no longer be manufactured
Discontinuance	MAX86160EFN+	N/A	17-Jul-2023	17-Jul-2023	Part can no longer be manufactured
Discontinuance	MAX86160EFN+T	N/A	17-Jul-2023	17-Jul-2023	Part can no longer be manufactured
Discontinuance	TMC-15-0291	N/A	17-Jul-2023	17-Jul-2023	Part can no longer be manufactured
Discontinuance	TMC-50-0176	N/A	17-Jul-2023	17-Jul-2023	Part can no longer be manufactured
Discontinuance	TMC-50-0182	N/A	17-Jul-2023	17-Jul-2023	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 17-Aug-2023