

# PRODUCT / PROCESS CHANGE NOTIFICATION PCN NO: PCN IN 230309-16

Issue Date: July 1<sup>st</sup>, 2023

# SUBJECT OF CHANGE:

MSL Level Adjustment for SMD LED Series Products

# **PRODUCTS AFFECTED:**

All Series. See part series listed below in "PRODUCT Series".

#### PRODUCT SPEC NUMBER:

IN-P18ATA	IN-P18ATR	IN-P18AT5UW	IN-P18AT5UW-7682
IN-P18ATA-8151	IN-P18ATG	IN-P18AT5UW-7845	IN-P18AT5UW-8152
IN-P18AT5UW-7688	IN-P18AT5UW-8209	IN-P18AT5UW-8205	

#### **REASON OF CHANGE:**

SMD LED packages were previous designated as MSL 3. Due to their encapsulation material and their assembly by reflow soldering, Inolux is now designating SMD packages as MSL 5a.

DESCRIPTION OF CHANGE:		
Major Change	Х	Minor Change

# PRODUCT IDENTIFICATION TO INDICATE CHANGE:

Product packaging bag will reflect change in handling requirement to MSL 5a.

PLEASE NOTE THIS IS A MSL REQUIREMENT ADJUSTMENT ONLY. THE PART REMAINS THE SAME. ALL SPECIFICATIONS, MATERIALS, AND PRODUCT CHARACTERISTICS REMAINS UNCHANGED.

#### **DATECODE OF CHANGE:**

Aug. 1<sup>st</sup>, 2023

#### **DATE TO BEGIN SHIPPING:**

Aug. 1<sup>st</sup>, 2023

#### ASSESSMENT:

In case of any questions please contact us at:

Issue By Department Telephone Ext. Fax

William Chang TM +1-408-8843871 +1-408-8449618 Holton Lee GM +1-408-8449698 +1-408-8449618

Expiration: 15 years V 1.0 F-008 Rev.1.0



# CUSTOMER FEEDBACK FORM to INOLUX PCN SMD LED Series MSL Level Adjustment

Dear Customer,

tomer Representative's name:

Expiration: 15 years V 1.0 F-008 Rev.1.0

**Signature** 

Santa Clara, CA, USA.