

Product Name:	HPL-552, HPL-346	
	PB RAH STB, PB VTR STB&PFPB+ RAH STB, PB+ VTR STB&PF	
Product Manager:	Huo-Rong Dai	
Subject:	Notification of Planned Change	
Distribution:	Affected customers	
Type of Change:	Location Change	
Change Description:	1. Assembly manufacturing capacity added for selected Power Blade products at Amphenol Cochin plant in addition to Amphenol Dongguan plant. 2. Production will be planned from either Amphenol Dongguan or Cochin plants depending upon the customer requirement and/or APH Demand Management. 3. Amphenol Dongguan plant will cater to the component supply requirements for both plants with no change in supply chain for parts. 4. There is no change of equipments in the assembly process.	
Reason for Change:	Addition of Assembly process for Power Blade and Power Blade Plus RAH and VR at Amphenol Cochin plant to support customers with "China plus one" manufacturing capacity.	
Affected Parts:	See "PB PB+ RAH VR PCN PNs.xlsx" file	
Effective Date of Change:	October,24 2023	
Last Time Buy Date:		
Earliest Disty Return Date:		
Last Time Shipment Date		
Datasheet Attached?	Yes	
Qual/Test Data Attached?	Yes	
Samples Availability Date:	24 July ,2023	
Available Alternatives?		
Questions?	Contact your local ACS Representative, or Product Manager	
	Huo-Rong Dai / Product Manager	
	Dai, Huo-Rong <Huo-Rong.Dai@fci.com>	

Note:

Customers should contact Product Line Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

MPN	Change	Effective Date
10089857-001A	Location Change	October 24 ,2023
10106116-2000502LF	Location Change	October 24 ,2023
10106116-3000003LF	Location Change	October 24 ,2023
10106116-3003002LF	Location Change	October 24 ,2023
10106116-4008001LF	Location Change	October 24 ,2023
10106116-5004001LF	Location Change	October 24 ,2023
10106116-6006K01LF	Location Change	October 24 ,2023
10106116-8000K01LF	Location Change	October 24 ,2023
10106116-8001K01LF	Location Change	October 24 ,2023
10106116-A004K01LF	Location Change	October 24 ,2023
10106116-A006K01LF	Location Change	October 24 ,2023
10106116-C009001LF	Location Change	October 24 ,2023
10106117-5005001LF	Location Change	October 24 ,2023
10106117-7000001LF	Location Change	October 24 ,2023
10106117-A009001LF	Location Change	October 24 ,2023
10106124-2005001LF	Location Change	October 24 ,2023
10106124-2202001LF	Location Change	October 24 ,2023
10106124-4000001LF	Location Change	October 24 ,2023
10106124-4001001LF	Location Change	October 24 ,2023
10106124-4001002LF	Location Change	October 24 ,2023
10106124-4004001LF	Location Change	October 24 ,2023
10106124-4004004LF	Location Change	October 24 ,2023
10106124-4006005LF	Location Change	October 24 ,2023
10106124-4006009LF	Location Change	October 24 ,2023
10106124-4006012LF	Location Change	October 24 ,2023
10106124-4006013LF	Location Change	October 24 ,2023
10106124-4403001LF	Location Change	October 24 ,2023
10106124-6000004LF	Location Change	October 24 ,2023
10106124-6004K01LF	Location Change	October 24 ,2023
10106124-7007001LF	Location Change	October 24 ,2023
10106124-8005003LF	Location Change	October 24 ,2023
10106124-8008001LF	Location Change	October 24 ,2023
10106124-9000002LF	Location Change	October 24 ,2023
10106124-9014001LF	Location Change	October 24 ,2023
10106124-9014002LF	Location Change	October 24 ,2023
10106124-A006002LF	Location Change	October 24 ,2023
10106124-C006001LF	Location Change	October 24 ,2023
10106124-E008001LF	Location Change	October 24 ,2023
10106124-F005K01LF	Location Change	October 24 ,2023
10106125-2004001LF	Location Change	October 24 ,2023
10106125-4000003LF	Location Change	October 24 ,2023
10106125-4006002LF	Location Change	October 24 ,2023
10106125-4006004LF	Location Change	October 24 ,2023
10106125-5005001LF	Location Change	October 24 ,2023

10106125-8000002LF	Location Change	October 24 ,2023
10106125-8004001LF	Location Change	October 24 ,2023
10106125-8015001LF	Location Change	October 24 ,2023
10106125-C812101LF	Location Change	October 24 ,2023
10106125-G018001LF	Location Change	October 24 ,2023
10106132-4009101LF	Location Change	October 24 ,2023
10106132-4027101LF	Location Change	October 24 ,2023
10106132-7008001LF	Location Change	October 24 ,2023
10106132-7008002LF	Location Change	October 24 ,2023
10106132-8000001LF	Location Change	October 24 ,2023
10106132-A005002LF	Location Change	October 24 ,2023
10106132-A007001LF	Location Change	October 24 ,2023
10106132-A008001LF	Location Change	October 24 ,2023
10106132-A016001LF	Location Change	October 24 ,2023
10106132-G000001LF	Location Change	October 24 ,2023
10106132-N003001LF	Location Change	October 24 ,2023
10106133-2000004LF	Location Change	October 24 ,2023
10106133-2000005LF	Location Change	October 24 ,2023
10106133-2012001LF	Location Change	October 24 ,2023
10106133-4009001LF	Location Change	October 24 ,2023
10106133-8007001LF	Location Change	October 24 ,2023
10106262-0002002LF	Location Change	October 24 ,2023
10106262-0006001LF	Location Change	October 24 ,2023
10106262-0009K01LF	Location Change	October 24 ,2023
10106262-0010001LF	Location Change	October 24 ,2023
10106262-0012K01LF	Location Change	October 24 ,2023
10106262-0017101LF	Location Change	October 24 ,2023
10106262-0203001LF	Location Change	October 24 ,2023
10106262-0314001LF	Location Change	October 24 ,2023
10106262-0527102LF	Location Change	October 24 ,2023
10106262-0613K01LF	Location Change	October 24 ,2023
10106262-0C05401LF	Location Change	October 24 ,2023
10106262-0D17001LF	Location Change	October 24 ,2023
10106262-0E02A01LF	Location Change	October 24 ,2023
10106262-0F08001LF	Location Change	October 24 ,2023
10106262-0G02A01LF	Location Change	October 24 ,2023
10106262-0G02K01LF	Location Change	October 24 ,2023
10106262-1617001LF	Location Change	October 24 ,2023
10106262-1C03004LF	Location Change	October 24 ,2023
10106262-1C03007LF	Location Change	October 24 ,2023
10106262-1C03012LF	Location Change	October 24 ,2023
10106262-1J02A01LF	Location Change	October 24 ,2023
10106262-2001003LF	Location Change	October 24 ,2023
10106262-2001505LF	Location Change	October 24 ,2023
10106262-2001K03LF	Location Change	October 24 ,2023
10106262-2007001LF	Location Change	October 24 ,2023

10106262-2600004LF	Location Change	October 24 ,2023
10106262-2G03A01LF	Location Change	October 24 ,2023
10106262-3001501LF	Location Change	October 24 ,2023
10106262-3019001LF	Location Change	October 24 ,2023
10106262-3037K01LF	Location Change	October 24 ,2023
10106262-4000006LF	Location Change	October 24 ,2023
10106262-4506001LF	Location Change	October 24 ,2023
10106262-4704003LF	Location Change	October 24 ,2023
10106262-4704K03LF	Location Change	October 24 ,2023
10106262-4A06001LF	Location Change	October 24 ,2023
10106262-5005K01LF	Location Change	October 24 ,2023
10106262-5029001LF	Location Change	October 24 ,2023
10106262-5203001LF	Location Change	October 24 ,2023
10106262-5206002LF	Location Change	October 24 ,2023
10106262-6002501LF	Location Change	October 24 ,2023
10106262-6002502LF	Location Change	October 24 ,2023
10106262-6003004LF	Location Change	October 24 ,2023
10106262-6003006LF	Location Change	October 24 ,2023
10106262-6003010LF	Location Change	October 24 ,2023
10106262-6010K01LF	Location Change	October 24 ,2023
10106262-6706001LF	Location Change	October 24 ,2023
10106262-6712001LF	Location Change	October 24 ,2023
10106262-7003003LF	Location Change	October 24 ,2023
10106262-7003006LF	Location Change	October 24 ,2023
10106262-7004001LF	Location Change	October 24 ,2023
10106262-7005003LF	Location Change	October 24 ,2023
10106262-7006001LF	Location Change	October 24 ,2023
10106262-7006004LF	Location Change	October 24 ,2023
10106262-7009001LF	Location Change	October 24 ,2023
10106262-7013K01LF	Location Change	October 24 ,2023
10106262-8003001LF	Location Change	October 24 ,2023
10106262-8004007LF	Location Change	October 24 ,2023
10106262-8802K01LF	Location Change	October 24 ,2023
10106262-9000007LF	Location Change	October 24 ,2023
10106262-9005001LF	Location Change	October 24 ,2023
10106262-9005003LF	Location Change	October 24 ,2023
10106262-9005004LF	Location Change	October 24 ,2023
10106262-9016K01LF	Location Change	October 24 ,2023
10106262-C004003LF	Location Change	October 24 ,2023
10106262-C007001LF	Location Change	October 24 ,2023
10106262-C007K01LF	Location Change	October 24 ,2023
10106262-C014K01LF	Location Change	October 24 ,2023
10106262-D006001LF	Location Change	October 24 ,2023
10106262-F000003LF	Location Change	October 24 ,2023
10106262-F203001LF	Location Change	October 24 ,2023
10106262-F203A01LF	Location Change	October 24 ,2023

10106262-J000001LF	Location Change	October 24 ,2023
10106262-K008001LF	Location Change	October 24 ,2023
10106262-T006001LF	Location Change	October 24 ,2023
10106263-0024001LF	Location Change	October 24 ,2023
10106263-0037001LF	Location Change	October 24 ,2023
10106263-0203004LF	Location Change	October 24 ,2023
10106263-0400001LF	Location Change	October 24 ,2023
10106263-0400003LF	Location Change	October 24 ,2023
10106263-0402001LF	Location Change	October 24 ,2023
10106263-0403002LF	Location Change	October 24 ,2023
10106263-2000501LF	Location Change	October 24 ,2023
10106263-2003001LF	Location Change	October 24 ,2023
10106263-2004001LF	Location Change	October 24 ,2023
10106263-5203K01LF	Location Change	October 24 ,2023
10106263-8004001LF	Location Change	October 24 ,2023
10106263-8037001LF	Location Change	October 24 ,2023
10106263-B006001LF	Location Change	October 24 ,2023
10106263-B006003LF	Location Change	October 24 ,2023
10106263-D006001LF	Location Change	October 24 ,2023
10106263-E304A01LF	Location Change	October 24 ,2023
10110432-001A	Location Change	October 24 ,2023

[illegible]

[illegible]

[illegible]