



## Product Change Notification

PCN No: MSS-23-0713-CCB-1013

KYEC Chunan to KYEC Tongluo IFLEX Test Transfer for ProSlic SI3228x and SI3229x

**Notification Date:** 07/24/2023

**Qualification Data Availability Date:** 07/07/2023

**Notification Period:** 90 days

**Sample Availability Date:** Not Applicable

**Proposed First Ship Date for Change:** 10/22/2023

**Last Date of Manufacture of Unchanged Product:** 10/31/2023

*Dear Valued Skyworks Customer:*

*Please be advised that Skyworks Solutions Inc. is introducing the following product change(s):*

### Description and Scope of Change

Relocate IFLEX tester used on SI3228x and SI3229x products from KYEC Chunan to Tongluo plant to integrate production testing of affected products into one KYEC plant

### Products Affected

SI32280-A-FM; SI32280-A-FMR; SI32280-A-GM; SI32280-A-GMR; SI32280-A-ZM1; SI32280-A-ZM1R; SI32280-A-ZM2; SI32280-A-ZM2R; SI32281-A-FM; SI32281-A-FMR; SI32281-A-GM; SI32281-A-GMR; SI32282-A-FM; SI32282-A-FMR; SI32282-A-GM; SI32282-A-GMR; SI32282-A-ZM1; SI32282-A-ZM2; SI32282-A-ZM2R; SI32283-A-FM; SI32283-A-FMR; SI32283-A-GM; SI32283-A-GMR; SI32283-A-ZM2; SI32283-A-ZM2R; SI32284-A-FM; SI32284-A-FMR; SI32284-A-GM; SI32284-A-ZM2; SI32284-A-ZM2R; SI32285-A-FM; SI32285-A-GM; SI32286-A-FM; SI32286-A-FMR; SI32286-A-GM; SI32286-A-GMR; SI32287-A-FM; SI32287-A-FMR; SI32287-A-GM; SI32287-A-GMR; SI32290-A-FM; SI32290-A-FMR; SI32290-A-GM; SI32290-A-GMR; SI32291-A-FM; SI32291-A-FMR; SI32291-A-GM; SI32291-A-GMR; SI32292-A-FM; SI32292-A-FMR; SI32292-A-GM; SI32292-A-GMR; SI32293-A-FM; SI32293-A-FMR; SI32293-A-GM; SI32293-A-GMR; SI32295-A-FM; SI32295-A-FMR; SI32295-A-GM; SI32295-A-GMR; SI32297-A-FM; SI32297-A-FMR; SI32297-A-GM; SI32297-A-GMR; SI32282-A-ZM1R; SI32283-A-ZM1; SI32283-A-ZM1R; SI32284-A-GMR; SI32284-A-ZM1; SI32284-A-ZM1R; SI32285-A-FMR; SI32285-A-GMR; SI32285-A-ZM1; SI32285-A-ZM1R; SI32285-A-ZM2; SI32285-A-ZM2R; SI32286-A-ZM1; SI32286-A-ZM1R; SI32286-A-ZM2; SI32286-A-ZM2R; SI32287-A-ZM1; SI32287-A-ZM1R; SI32287-A-ZM2; SI32287-A-ZM2R; SI32281-A-ZM1; SI32281-A-ZM1R; SI32281-A-ZM2; SI32281-A-ZM2R

### Method for Identifying Changed Product

Full product change traceability is maintained by: date code

### Reason for Change

Testers are consolidating to one KYEC test plant location

### Anticipated Impact on Form, Fit Function, Reliability, Quality or Safety

No customer impact is anticipated with this change; there is no change to form, fit, function, reliability, quality or safety.

### Qualification Plan Summary

Test correlation between KYEC Chunan and KYEC Tongluo established through splitting qual lots.

### Launch Plan

Upon completion of the notification period, change will be implemented.

*Please contact your Skyworks customer service representative with any questions or comments regarding this change. If you are unsure whom to contact, please email Skyworks Change Management at [Skyworks.CCB@Skyworksinc.com](mailto:Skyworks.CCB@Skyworksinc.com).*

### Skyworks Solutions, Inc.

20 Sylvan Road, Woburn, MA 01801

USA: (781) 376-3000 • Asia: 886 2 2735 0399

Europe: 33 (0)1 43548540 • Fax: (781) 376-3300

On the Web: [www.skyworksinc.com](http://www.skyworksinc.com)