

Before Picture

Overview

 This notification is to inform you that Molex will no longer support this product because of "Supplier constraint / Low demand" and they are stating that they cannot produce the part."

Part Number Impact

- See attached impacted parts list
- Replacement for this part
 - No Replacement
- See above for the LTB and LTS date

For assets that are customer owned, the owner has 90 days after the last time ship date to claim the tooling."

You may address inquires regarding this PCN by clicking on the below link mailto:pcn_coordinator@molex.com?subject=PCN_Notification:514040 or contact your Local Sales Engineer.

Note: While responding, please retain "PCN Notification: PCN Notification: 514040" in the e-mail Subject line for faster response.

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL (800) 786-6539 www.molex.com

[&]quot;After the last time ship date, Molex will no longer manufacture the products included within this notification and all related tooling will be decommissioned.

PCN No Part List

514040 <u>0448120002</u>

514040 0448120003

514040 <u>0448120004</u>

514040 <u>0448120005</u>

514040 <u>0448120006</u>

514040 <u>0448120007</u>

514040 <u>0448120008</u>

514040 <u>0448120009</u>

514040 <u>0448120010</u>

514040 <u>0448120012</u>

514040 <u>0448120014</u>

514040 <u>0448120015</u>

514040 <u>0448120016</u>