

<b>Product Name:</b>	HPL – 664		
	MINITEK 1.2MM		
<b>Product Manager:</b>	Gino.Liu		
<b>Subject:</b>	Notification of Change with Immediate Effectivity		
<b>Distribution:</b>	Affected customers		
<b>Type of Change:</b>	End-of-Life		
<b>Change Description:</b>	End-of-Life for Minitek 1.2mm		
<b>Reason for Change:</b>	The involved part numbers cannot be manufactured anymore due to worn out tooling. Unfortunately we cannot accept new orders. There are no drop-in replacement parts available.		
<b>Affected Parts:</b>	See Affected parts.xls file		
<b>Effective Date of Change:</b>	August,06 2024		
<b>Last Time Buy Date:</b>	06 February ,2024		
<b>Earliest Disty Return Date:</b>	06 November ,2023		
<b>Last Time Shipment Date</b>	06 August ,2024		
<b>Datasheet Attached?</b>	Yes		
<b>Qual/Test Data Attached?</b>	Yes		
<b>Samples Availability Date:</b>			
<b>Available Alternatives?</b>			
<b>Questions?</b>	Contact your local ACS Representative, or Product Manager		
	Gino.Liu / Product Manager		
	Gino.Liu@fci.com		

**Note:**

Customers should contact Product Line Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

MPN	Change	Effective Date
10125836-03-001SP	END OF LIFE	AUGUST 06, 2024
10125836-04-001	END OF LIFE	AUGUST 06, 2024
10125836-04-001SP	END OF LIFE	AUGUST 06, 2024
10125836-06-001	END OF LIFE	AUGUST 06, 2024
10125836-06-001SP	END OF LIFE	AUGUST 06, 2024
10125836-03-001	END OF LIFE	AUGUST 06, 2024
10125837-001GLF	END OF LIFE	AUGUST 06, 2024
10125837-001SPGLF	END OF LIFE	AUGUST 06, 2024
10125839-03RAEHLF	END OF LIFE	AUGUST 06, 2024
10125839-04RAEHLF	END OF LIFE	AUGUST 06, 2024
10125839-06RAEHLF	END OF LIFE	AUGUST 06, 2024