

## Product Change Notice

Issue Date: 30-July-2023

**Change Description:**

Introduction of new LED die

**Parts Affected:**

ASM6-SL91-NST0H
ASM6-SLD1-NST0H
ASM6-SW91-NMQBH
ASM6-SW91-NMQCH
ASM6-SW91-NNRDH
ASM6-SW91-NNRKH
ASM6-SW91-NPREH
ASM6-SW91-NPRFH
ASM6-SW91-NPRHH
ASM6-SWD1-NPSBH
ASM6-SWD1-NPSCH
ASM6-SWD1-NQTDH
ASM6-SWD1-NQTEH
ASM6-SWD1-NQTFH
ASM6-SWD1-NQTHH
ASM6-SWD1-NQTKH

**Description and Extent of Change:**

New die has been qualified as a replacement to existing LED die.

**Reasons for Change:**

Discontinuation of current LED die supply.

**Effect of Change on Fit, Form, Function, Quality, or Reliability:**

There will be no change in fit, form, function, quality or reliability of the final product.

**Effective Date of Change:**

Part with the above change will commence 90 days after the issuance date above.

1. Broadcom will continue to ship parts from both LED die sources after the implementation date until the inventory of the existing LED die source is fully depleted.
2. The shipment may contain parts with either the existing or new die source after the implementation date.

**Qualification Data:**

Qualification data will be available upon request.

---

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.