

<b>Product Name:</b>	HPL – 677	
	DuraEV	
<b>Product Manager:</b>	Tony P Paul	
<b>Subject:</b>	Notification of Change with Immediate Effectivity	
<b>Distribution:</b>	Affected customers	
<b>Type of Change:</b>	Design Change	
<b>Change Description:</b>	1. Addition of a stopper feature on the socket housing as part of product improvement 2. High tensile & orange colour O-Rings introduced as part of product improvement	
<b>Reason for Change:</b>	Product continual improvement	
<b>Affected Parts:</b>	See Affected parts.xls file	
<b>Effective Date of Change:</b>	August,17 2023	
<b>Last Time Buy Date:</b>		
<b>Earliest Disty Return Date:</b>		
<b>Last Time Shipment Date</b>		
<b>Datasheet Attached?</b>	Yes	
<b>Qual/Test Data Attached?</b>	Yes	
<b>Samples Availability Date:</b>	08 August ,2023	
<b>Available Alternatives?</b>		
<b>Questions?</b>	Contact your local ACS Representative, or Product Manager	
	Tony P Paul / Product Manager	
	Tony.Paul@amphenol-fci.com	

**Note:**

Customers should contact Product Line Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

# Amphenol

COMMUNICATIONS SOLUTIONS

**DuraEV PCN  
Socket Stopper**

2<sup>nd</sup> Aug, 23

**ACPI**




# 1. Addition of Stopper Feature in the Socket Housing

**Change:** Addition of four stopper ribs on the socket housing as part of product continual improvement

**Affected PNs:** Refer next slide

**Implementation Date:** CW31 in AFCI Assembly line

: Shipment to customer based on stock depletion



# Affected PNs

- |                        |                        |   |
|------------------------|------------------------|---|
| 1. AU10169535-G24EWLF  | 17. AU10165424-N24DBLF | 33. AU10169535-J24CPLF  |
| 2. AU10169535-G24EWLF  | 18. AU10169534-N24AFLF | 34. AU10169535-M24ACLF  |
| 3. AU10165424-G24BALF  | 19. AU10169535-G24BBLF | 35. AU10169535-M24AYLF  |
| 4. AU10165424-G24BBLF  | 20. AU10169535-G24BCLF | 36. AU10169535-N24DPLF  |
| 5. AU10165424-G24BDLF  | 21. AU10169535-G24BDLF | 37. AU10169535-P24ADLF  |
| 6. AU10165424-G24BPLF  | 22. AU10169535-G24BMLF | 38. AU10169535-x24xxLF<br>(Generic Part Number for<br>listing all combinations<br>possible) |
| 7. AU10165424-G24EBLF  | 23. AU10169535-G24BNLF |   |
| 8. AU10165424J24CABLF  | 24. AU10169535-G24BYLF |   |
| 9. AU10165424-J24CALF  | 25. AU10169535-G24EBLF |   |
| 10. AU10165424-J24CBLF | 26. AU10169535-G24EPLF |   |
| 11. AU10165424-J24CDLF | 27. AU10169535-J24CALF |   |
| 12. AU10165424-J24CKLF | 28. AU10169535-J24CALF |   |
| 13. AU10165424-J24CPLF | 29. AU10169535-J24CBLF |   |
| 14. AU10165424-J24GALF | 30. AU10169535-J24CDLF |   |
| 15. AU10165424-M24ABLF | 31. AU10169535-J24CELF |   |
| 16. AU10165424-M24APLF | 32. AU10169535-J24CHLF |   |