



Product Change Notification

Date Issued :	August 18, 2023	PCN Number :	513841
Reason for Change :	Change Supplier		
Description of Change :	This notification is to inform about addition of new metal strip supplier for part number 648971898 as new source to ensure continuity of supply for 53398 Series. No changes will be made to product as part of this change		
Reason for Short Notice :	Special Request		
Assessment of Change :	First Article Inspection		
Planned Implementation Date :	May 31, 2024		
Sample Availability Date:	November 29, 2023		
Internal Molex Qualification Date :	December 22, 2023		
Last date to request Samples by Customer : November 29, 2023			
Traceability Code Markings / Date :	Date code		

Before Picture

Overview

- Current metal strip for part number 648971898 are supply by Anhui Xinke Copper. Due to these supply constraints, Molex Malaysia identified an internal shortage of metal supply which would create a challenge to fulfill all orders. This change is to ensure continuity of supply for customers. Therefore, an alternative source has been identified for the product families.

After Picture

Overview

- This notification is to inform about addition of new metal strip supplier (Ningbo Xingye Shengtai Group and Powerway Alloy) for part number 648971898 as new source to ensure continuity of supply for 53398 Series. No changes will be made to product as part of this change.

Before			After		
Part	Material	Supplier/Maker	Part	Material	Supplier/Maker
648971898	Phosphor bronze C51000	AnHui Xinke	648971898	Phosphor bronze C51000	AnHui Xinke Powerway Alloy Ningbo Xingye Shengtai

- Molex Malaysia Part Number(s) Affected: Refer to attached for the impacted parts.
- Product Impact
 - There is no impact to the fit, form or functional specification on the product as part of this change. Molex Malaysia may use this metal strip in future production.
- Qualification reports and samples available upon request.

2

Molex Confidential Information
© 2016 Molex – All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibited.



RELEASED

You may address inquiries regarding this PCN by clicking on the below link
mailto:pcn_coordinator@molex.com?subject=PCN_Notification:513841
 or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : **PCN Notification: 513841** " in the e-mail Subject line for faster response.

Molex, LLC
 2222 Wellington Court
 Lisle, IL 60532
 TEL (800) 786-6539
www.molex.com

PCN No Part List

513841 [0533980267](#)
513841 [0533980271](#)
513841 [0533980276](#)
513841 [0533980367](#)
513841 [0533980371](#)
513841 [0533980376](#)
513841 [0533980467](#)
513841 [0533980471](#)
513841 [0533980476](#)
513841 [0533980567](#)
513841 [0533980571](#)
513841 [0533980576](#)
513841 [0533980667](#)
513841 [0533980671](#)
513841 [0533980676](#)
513841 [0533980767](#)
513841 [0533980771](#)
513841 [0533980867](#)
513841 [0533980871](#)
513841 [0533980876](#)
513841 [0533980967](#)
513841 [0533980971](#)
513841 [0533980976](#)
513841 [0533981067](#)
513841 [0533981071](#)
513841 [0533981171](#)
513841 [0533981271](#)
513841 [0533981371](#)
513841 [0533981467](#)
513841 [0533981471](#)
513841 [0533981571](#)
513841 [0533984002](#)
513841 [0533984003](#)
513841 [0533984004](#)
513841 [0533984005](#)
513841 [0533984006](#)
513841 [0533984008](#)
513841 [0533984010](#)
513841 [0533984012](#)
513841 [0533984014](#)
513841 [0533985002](#)
513841 [0533985003](#)
513841 [0533985004](#)
513841 [0533985008](#)
513841 [0533988604](#)

