



Product / Process Change Notification (PCN)

PCN ID#: 195

Title: supplier change for GL42013SC & GK46075

Change: Permanent

Honeywell Contact

Name: Dzul, Jorge

E-mail: Jorge.Dzul@Honeywell.com

Title: Sr Quality Engineer

Product Information

Affected parts and revisions:

GLAC01A1A CDILBS1W CDIRBS1W GLAA01A GLAA01A1A GLAA01A1B GLAA01A2A GLAA01A2B GLAA01A4J
GLAA07A GLAA07A1B GLAA20A1B GLAA20A2A GLAA20A2B GLAA20A4J GLBB02A GLZ1AA GSAA01A1B
GSXA01A1A GSXA42A1E GLBA02A1B GSAA20A1B GLHB24A1B GLAC20A1A GLAB01A2B GLGA12A1B
GSAA20A1A GSXA01A GSAA41A1B GSAB01A1B GSXA07A1A GSXC07A1E GLAC01A2A GSAC22A1B GSXA46A1E
GLAC20A1B GLAB20A1A GSXA20A1A CDILBP1W CDIRBP1W GLAA20A1A GLAA22A1B GLAB01A1B GLAB20A1B
GSAB20A1B GLAA01A2Y GLAB20A4J GLAC01A2B GLAC07A1B GLAC20A2B GSAA20A5A GLAB01A-5

Does the part number change? False

Type of Change:

Supplier- Manufacturer

Change Description:

Current supplier is having some logistic issues to continue supplying the GL42013SC & GK46075 used for a different models, Honeywell is moving to another supplier in order to avoid future material shortage, making the necessary adjustments to prevent a customer line down

Reason for change:

Current supplier is having some logistic issues to continue supplying the GL42013SC & GK46075.

Justification for change:

Honeywell is moving to another supplier in order to avoid future material shortage, making the necessary adjustments to prevent a customer line down.

Product Identification to distinguish the change:

date code 2335

Samples (If required): Not applicable

Change Implementation Date: 2023-09-01

Honeywell is committed to providing you with a superior level of customer service. Please e- mail to [contact](#)

listed above for additional information regarding this communication.

G-AST-FRM-QA.2

EFFECTIVE DATE: 3-29-22

REVISION: 0