molex

Product Change Notification

HOLEX	rioduct change Nothication		
Date Issued :	August 30, 2023	PCN Number :	514056
Reason for Change :	Manufacturing Process Change (Molex)		
Description of Change :	This notification is to inform you about manufacturing process change for the part/s listed in this notice is changing. No changes will be made to product as part of this change.		
Assessment of Change :	Supplier Qualification Test Report/s		
Planned Implementation Date:	March 01, 2024		
Sample Availability Date:	December 01, 2023		
Internal Molex Qualification Date :	December 11, 2023		
Last date to request Samples by Cust	omer: December 10, 2023		
Traceability Code Markings / Date :	Date code		

Before Picture

■ Change the metal shell plating from "overall tin" to "matte tin plated at solder tail area, other area nickel plating"

Before change:

BRIGHT TIN PLATED.
THICKNESS= 1.25 PM/50 PMNCH MINIMUM
UNDER PLATE: NICKEL (Ni).

After change:

MATTE TIN PLATED AT SOLDER AREA THICKNESS=80~110MICROINCH. UNDER PLATING: NICKEL(Ni), ALL OVER SURFACE. THICKNESS=50 MICROINCH MINIMUM.

After Picture

Overview

- In order to improve product environment performance since feedback from customer the metal shell easy discolored after passing IR.
- Product Impact:
 No impact to fit, form or function;
- Part Number Impact
 See attached impacted parts list
- Qualification Reports and samples available upon request after the date shown above



You may address inquires regarding this PCN by clicking on the below link mailto:pcn_coordinator@molex.com?subject=PCN_Notification:514056 or contact your Local Sales Engineer.

Note: While responding, please retain "PCN Notification: PCN Notification: 514056" in the e-mail Subject line for faster response.

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL (800) 786-6539 www.molex.com

PCN No Part List

514056 <u>0676430910</u>

514056 0676432910

514056 <u>0676432911</u>

514056 <u>0676433910</u>

514056 <u>0676433911</u>

514056 2222110185