



na.industrial.panasonic.com

industrial@us.panasonic.com

1-800-344-2112

Not Recommended for New Designs: 16TQC33MYFS POSCAP Capacitors

NRFND.PG91.09.06.2023 09.06.2023

About This Notice:	To our valued customers: The following Panasonic Industry part numbers are being marked as Not Recommended for New Designs (NRFND) and will eventually be discontinued. We understand that this may cause some inconvenience, but we assure you that we have recommended alternatives available. For further details, please reference the attached documents or contact us directly. We appreciate your business and look forward to continuing to serve your needs.
Features:	N/a
Effective Date:	Immediate.
Affected Part(s) and/or Replacement(s):	Affected Part: 16TQC33MYFS Replacement(s): See attached Affected Parts List or contact Panasonic for more information.
Datasheet(s):	See attached Datasheet.
Notes:	N/a