

INTRODUCTION OF ALTERNATIVE GREASES ON P11A, 148, P11D, 248 MODEL

For further information, please contact your regional Vishay office.

CONTACT INFORMATION

Americas

Pierre Lesur
71 chemin de la Mauniere
-
Hyerres France 83400
Phone: +33494123050
Fax: +33494123051
pierre.lesur@vishay.com

Europe

Pierre Lesur
71 chemin de la Mauniere
-
Hyerres France 83400
Phone: +33494123050
Fax: +33494123051
pierre.lesur@vishay.com

Asia

Pierre Lesur
71 chemin de la Mauniere
-
Hyerres France 83400
Phone: +33494123050
Fax: +33494123051
pierre.lesur@vishay.com

Description of Change: Introduction of an alternative grease

Reason for Change: Due to discontinuation of grease material, we have secured grease provision thanks to a new grease source.

Grease is used to reduce wear between wiper and collector and for electrical noise reduction.

We have qualified this alternative grease. If you require a specific qualification process, please let us know ASAP

Expected Influence on Quality/Reliability/Performance: No influence on Quality/Reliability/Performance, according to qualification results

Part Numbers/Series/Families Affected: P11A*, 148*, P11D*, 248*,

Vishay Brand(S): Vishay Sfernice

Time Schedule:

Start Shipment Date: Mon Nov 6, 2023

Sample Availability: W40

Product Identification: Date code W45

Qualification Data: Available on request

This PCN is considered approved, without further notification, unless we receive specific customer concerns before Mon Oct 23, 2023 or as specified by contract.

Issued By: Pierre Lesur, pierre.lesur@vishay.com

Vishay Material Code

14810A0BHSX10102KA
14810A0BHSX10103KA
14810A0BHSX10502KA
14810F0GJSX10102KA
14810F0GJSX10103KA
14810F0GJSX10502KA
14820F0GJSX13102KA
14820F0GJSX13103KA
14821F0GJSX13102KA
14821F0GJSX13103KA
248BBHS0XB25103MA
248BBHS0XB25104MA
248BBHS0XB25252MA
248BBHS0XB25503MA
248FGJS0XB25104MA
248FGJS0XB25502MA
248FGJSPXB25103MA
P11A2T0AJSZ00473KA