

<b>Product Name:</b>	666 - CROSSMATE		
	CROSSMATE		
<b>Product Manager:</b>	Gino Liu		
<b>Subject:</b>	Notification of Planned Change		
<b>Distribution:</b>	Affected customers		
<b>Type of Change:</b>	End-of-Life		
<b>Change Description:</b>	End of Life CROSSMATE partnumber series 10150535 / 10150526 / 10150537 / 10156148		
<b>Reason for Change:</b>	Based on customer and market feedback, CrossMate development will be suspended.		
<b>Affected Parts:</b>	10150535 / 10150526 / 10150537 / 10156148		
<b>Effective Date of Change:</b>	September,21 2024		
<b>Last Time Buy Date:</b>	21 March ,2024		
<b>Earliest Disty Return Date:</b>	21 December ,2023		
<b>Last Time Shipment Date</b>	21 March ,2025		
<b>Datasheet Attached?</b>	Yes		
<b>Qual/Test Data Attached?</b>	Yes		
<b>Samples Availability Date:</b>			
<b>Available Alternatives?</b>			
<b>Questions?</b>	Contact your local ACS Representative, or Product Manager		
	Gino Liu / Product Manager		
	gino.liu@fci.com		

**Note:**

Customers should contact Product Line Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .

## MPN

10150535-020HLF  
10150535-030HLF  
10150535-040HLF  
10150535-060HLF  
10150535-070HLF  
10150535-080HLF  
10150535-090HLF  
10150535-100HLF  
10150535-110HLF  
10150535-120HLF  
10150535-050HLF  
10150526-0211HLF  
10150526-0311HLF  
10150526-0411HLF  
10150526-0611HLF  
10150526-0711HLF  
10150526-0811HLF  
10150526-0911HLF  
10150526-1011HLF  
10150526-1111HLF  
10150526-1211HLF  
10150526-0511HLF  
10150537-002LF  
10156148-001  
10156148-001LF