

Product Change Notice

PCN-S230901

Date of Publication: 2023/9/28

Description of Change:

Update BIOS from MR3 to MR5 with patch version to resolve Intel's Elkhartlake CPU auto reboot issue on the last BIOS version.

Affected Product Model No.:

SOM-2532 Standard P/N and related T-P/N.

Original P/N	Replacement P/N
1. BIOS: 1420056682 BIOS SOM-2532 0060V200 CS:7C75 W25R256JWEIQ	1. BIOS: 1420058467 BIOS SOM-2532 0060V300 CS:5117 W25R256JWEIQ

Potential impacts to customers:

PCB: no change required

BIOS: [change required](#)

EC Firmware: no change required

OS: [change required](#)

Driver: [change required](#)

Function: no impact

Ordering Information:

No change

Impact of change & recommended action date:

STD-P/N already adopted new BIOS by ECOM-206532 & ECOM-206564 from September, 2023

For T-P/N, please get customers' approval and adopt these new parts as replacements by TPS.

Key Information & Milestones:

ECOM number: ECOM-206532 & ECOM-206564

ECOM released date: **September, 2023**

Last Time Buy date: **N/A**

Issue by	PM: Olive Wang
----------	----------------