

PRODUCT CHANGE NOTIFICATION

Product Category FIBER DISTRIBUTION 20230921-1

Product Group CONNECTIVITY & PATHWAYS

ISSUE DATE: 21-Sep-23

IMPACTED REGIONS: ☒ NA ☒ EMEA ☒ LATAM ☒ AP

REASON FOR CHANGE: ☒ DISCONTINUATION
☐ OTHER

DESCRIPTION OF CHANGE: (Required)

We are Obsoleteing multiple Fiber enclosures some due to lack of sales and some are being replaced with our new enclosure FRE1UBL.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2023	12	20

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSVM@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com	
LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerservice@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA FORM C2-1003 DATE: 06APR21 APPR: MURILLO	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com

		Discontinuation
IMPACTED PART NUMBER(s)	Replacement Part 1	Date
FMD1	FRE1UBL	20-DEC-2023
FCE1UA	FRE1UBL	20-DEC-2023
FCE1UAWH	FRE1UBL	20-DEC-2023
FMT1A	FMT1	20-DEC-2023
FMT1AWH	FMT1	20-DEC-2023
FMT2A	FMT2	20-DEC-2023
CFAPPBL2A	NO-REPLACEMENT	20-DEC-2023
CFAPPBL1A	NO-REPLACEMENT	20-DEC-2023