

PRODUCT CHANGE NOTIFICATION

Product Category COPPER CONNECTORS

Product Group ENTERPRISE CONNECTIVITY

ISSUE DATE: 4-Oct-23

IMPACTED REGIONS: ☒ NA ☒ EMEA ☒ LATAM ☒ AP

REASON FOR CHANGE: ☐ DISCONTINUATION
☒ OTHER

DESCRIPTION OF CHANGE: (Required)

Panduit is eliminating printed instructions from several of our modular plug products. Customers are encouraged to scan the carton labels and/or use the Install-It app for these products, and only print the instructions if absolutely necessary.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2023	11	1
Old product discontinuation date*			

IMPACTED PART NUMBER(s)

SP6X88SD-C

SP6X88-C

SP6X88P-C

SPS626-C

MP588

MPF588

SPS688-C