



Product Change Notification / BLAS-23LTBB967

Date:

24-Oct-2023

Product Category:

Voice Audio

PCN Type:

End of Life

Notification Subject:

eSign# EOL0000017: End of Life (EOL) of MT9074AP1, MT9074APR1 and MT9076BB1 catalog part numbers (CPN).

Affected CPNs:

[BLAS-23LTBB967_Affected_CPN_10242023.pdf](#)

[BLAS-23LTBB967_Affected_CPN_10242023.csv](#)

Notification Text:

PCN Status:End of Life (EOL) Notification

Microchip Parts Affected:Please open one of the files found in the Affected CPNs section.

NOTE: For your convenience Microchip includes identical files in two formats (.pdf and .xls).

EOL Description:The MT9074AP1, MT9074APR1 and MT9076BB1 catalog part numbers (CPN) will be moving to End of Life (EOL) status effective today. These catalog part numbers will no longer be offered after February 12, 2024. Please review the attached parts affected list below for details about replacement parts if applicable.

Note: If replacement parts are not listed in the attached list please contact your **Local Sales Representative**

Reason for EOL:No longer have manufacturing support for the CPN listed in the attachment.

Estimated Effective Dates:Customers affected by this EOL notice are advised to place last time buy (LTB) orders as follows:

Last date for bookings (LTB): December 11, 2023

Last date for shipments (LTS): February 12, 2024

Revision History:October 25, 2023: Issued EOL notification.

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

MT9074AP1

MT9074APR1

MT9076BB1