

# Skywire® NL-SW-LTE-SVZM20

## Product Change Notification

NimbeLink Corp

Updated: June 2018



© NimbeLink Corp. 2018. All rights reserved.

NimbeLink Corp. provides this documentation in support of its products for the internal use of its current and prospective customers. The publication of this document does not create any other right or license in any party to use any content contained in or referred to in this document and any modification or redistribution of this document is not permitted.

While efforts are made to ensure accuracy, typographical and other errors may exist in this document. NimbeLink reserves the right to modify or discontinue its products and to modify this and any other product documentation at any time.

All NimbeLink products are sold subject to its published Terms and Conditions, subject to any separate terms agreed with its customers. No warranty of any type is extended by publication of this documentation, including, but not limited to, implied warranties of merchantability, fitness for a particular purpose and non-infringement.

NimbeLink and Skywire are registered trademarks of NimbeLink Corp. All trademarks, service marks and similar designations referenced in this document are the property of their respective owners.

# Table of Contents

<b>Table of Contents</b>	<b>2</b>
<b>Introduction</b>	<b>3</b>
<b>Migration Overview</b>	<b>3</b>
<b>Last Time Buy Date</b>	<b>3</b>
<b>Contact</b>	<b>3</b>

# 1. Introduction

Over their lifetime, Skywire® modems may incur several firmware updates provided from the module manufacturers. These updates will improve communication, fix bugs, and add features to the module and resulting modem functionality. NimbeLink will stay current with the latest firmware releases. It is recommended that customers also test and apply these new firmware versions when they become available. The Suppliers of the modules used in the NimbeLink Modems will from time to time EOL, End of Life, both FW and the module HW devices. NimbeLink will provide timely commercially reasonable effort to communicate these changes to our modem customers.

The NL-SW-LTE-SVZM20 Skywire® modem is manufactured using Sequans firmware version LR5.1.1.0-32110. Sequans has since released new firmware, release LR5.1.3.0-MR3.2-37120, which is their latest Firmware Maintenance Release, (MR.) This MR includes several updates, including:

- Numerous AT command updated to align with AT Command Manual
- Numerous bug fixes and lockup fixes
- The USB port now defaults to an AT command interface
- Cellular registration improvements
- Verizon Thingspace stack added

The NL-SW-LTE-SVZM20 is being superseded by the NL-SW-LTE-SVZM20-B which will ship with the latest firmware released by Sequans, release LR5.1.3.0-MR3.2-37120.

## 2. Migration Overview

Customers with existing products can update to version LR5.1.3.0-MR3.2-37120 via a firmware update; firmware update instructions are provided in application note [1001541](#).

All designs should migrate to part number NL-SW-LTE-SVZM20-B, which is specific to firmware version LR5.1.3.0-MR3.2-37120.

### 3. Last Time Buy Date

Customers using NL-SW-LTE-SVZM20 should move to NL-SW-LTE-SVZM20-B, NL-SW-LTE-SVZM20 is Not Recommended for New Design, NRND, but is still an orderable part number and can be purchased as a custom order. Contact [Sales@nimbelink.com](mailto:Sales@nimbelink.com) for quotation and lead-time.

Customers starting new designs should start with NL-SW-LTE-SVZM20-B. From this date forward the standard orderable part number from NimbeLink will be the NL-SW-LTE-SVZM20-B.

### 4. Contact

For further information please contact NimbeLink sales team at:  
<http://nimbelink.com/contact-us/>