

Amphenol East Asia Electronic Technology (Shenzhen) Cor. Ltd
Block A3/4, the 4th Industrial District, Industrial Headquarter, Dong Keng Road, Gong Ming
Town, Shen Zhen City, 518132 China
Tel: +86 755 2717 7945

Apr 14, 2022

Announcement on EOL of D sub HR series crimping contact with 10Kpcs package part numbers

Dear valued customers,

Due to package of 10K/reel is connected by two 5K/reel, and some customers complained they couldn't accept the joint. Now factory can't support 10K/reel any more. Sorry we have to announce the immediate end of life of below part numbers and advise replacement part number as well.

We are very sorry for the inconvenience it may cause.

Part Number	Replacement
L17HRD2F0110G	L17HRD2F015G
L17HRD2F0110K	L17HRD2F015K
L17HRD2F0210G	L17HRD2F025G
L17HRD2F0210K	L17HRD2F025K
L17HRD2F0410G	L17HRD2F045G
L17HRD2F0410K	L17HRD2F045K
L17HRD2F1110G	L17HRD2F115G
L17HRD2F1110K	L17HRD2F115K
L17HRD2F1410G	L17HRD2F145G
L17HRD2F1410K	L17HRD2F145K
L17HRD2M0110K	L17HRD2M015K
L17HRD2M0210K	L17HRD2M025K
L17HRD2M0410G	L17HRD2M045G
L17HRD2M0410K	L17HRD2M045K
L17HRD2M1110G	L17HRD2M115G

Amphenol

Amphenol East Asia Electronic Technology (Shenzhen) Cor. Ltd
Block A3/4, the 4th Industrial District, Industrial Headquarter, Dong Keng Road, Gong Ming
Town, Shen Zhen City, 518132 China
Tel: +86 755 2717 7945

L17HRD2M1110K	L17HRD2M115K
L17HRD2M1410G	L17HRD2M145G
L17HRD2M1410K	L17HRD2M145K
L17HRD2M0110G	L17HRD2M015G
L17HRD2M0210G	L17HRD2M025G
L17HRD2F1210G	L17HRD2F125G
L17HRD2F0110G	L17HRD2F015G
L17HRD2F0210G	L17HRD2F025G
L17HRD2F0410G	L17HRD2F045G
L17HRD2F1110G	L17HRD2F115G
L17HRD2F1410G	L17HRD2F145G
L17HRD2M0410G	L17HRD2M045G
L17HRD2M1110G	L17HRD2M115G
L17HRD2M1410G	L17HRD2M145G
L17HRD2M0110G	L17HRD2M015G
L17HRD2M0210G	L17HRD2M025G
L17HRD2F1210G	L17HRD2F125G

Yours sincerely

Helen Xiong

Global Product Manager, Dsub and Centronic Product Lines

Amphenol East Asia Electronic Technology (Shenzhen) Cor. Ltd