



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300

Product Discontinuation

PDN-ICC-9100-2023

Business Unit	Product Line Code	Type of Change	Action	Date of Issue
ICC - Industrial Cabinet	BE1	Product Discontinuation	Notify Distributors and Field	10/18/2023

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Description for Product Discontinuation

Discontinuation of PV fuse portfolio due to the changing market requirements.

Stock Status

Can existing stock still be used? Yes

Is mixture of stock acceptable? No

Transaction Dates

Last Buy from Phoenix Contact: 9/30/2023

Last Scheduled Ship from Phoenix Contact: 11/30/2023

Should you have any issues with the timeline or content of this product discontinuation, please contact Phoenix Contact using the information below. Customers should acknowledge receipt of the PDN within 30 days of delivery of the PDN; provided, however, that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

Eric Silvestri
esilvestri@phoenixcontact.com

Thank you,

Cory Myer

Associate Product Marketing Manager ICC



Phoenix Contact Inc.
P.O. BOX 4100
Harrisburg, PA 17111-0100
Phone: 717-944-1300

Product Discontinuation

Discontinued Part #	Type Description	Replacement Part #	Type Description
3062767	FUSE 10,3X85 4A PV		
3062768	FUSE 10,3X85 6A PV		
3062769	FUSE 10,3X85 8A PV		
3062770	FUSE 10,3X85 10A PV		
3062771	FUSE 10,3X85 12A PV		
3062778	FUSE 10,3X38 6A PV A		
3062780	FUSE 10,3X38 10A PV A		
3062781	FUSE 10,3X38 12A PV A		
3062782	FUSE 10,3X38 16A PV A		