

PRODUCT CHANGE NOTIFICATION

Product Category INDUSTRIAL NETWORKS CABLE & CONNECTIVITY **20231102-1**

Product Group INDUSTRIAL NETWORKS

ISSUE DATE: 2-Nov-23

IMPACTED REGIONS: ☒ NA ☒ EMEA ☒ LATAM ☒ AP

REASON FOR CHANGE: ☒ DISCONTINUATION
☐ OTHER

DESCRIPTION OF CHANGE: (Required)

Parts are being discontinued in order to streamline the product offering. Thank you for your ongoing support.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2023	11	2
Old product discontinuation date*	2024	1	31

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1	Replacement Part 2
ESFLHT5C02FGR-Z	No Replacement	NO-REPLACEMENT	
ESFLHT5C02FGRZC	No Replacement	NO-REPLACEMENT	
ESFLHT5C02SGR-Z	No Replacement	NO-REPLACEMENT	
ESFLHT5C02FGR-X	No Replacement	NO-REPLACEMENT	
ESFLHT5C02GR-X	No Replacement	NO-REPLACEMENT	
ESFLHT5C02SGRZC	No Replacement	NO-REPLACEMENT	
IUC5C04ABL-CEG	Direct	ISFCH6X04ABL-UG	ISFCH6X04ATL-UG
IFC5C04BBL-CEG	Direct	ISFCH6X04BBL-UG	ISFCH6X04BTL-UG
IFRH5C04BL-UG	Direct	IFRH6X04BL-UG	IFRH6X04TL-UG
IFRH5C04BL-UG-S	Direct	IFRH6X04BL-UG	IFRH6X04TL-UG
IFRH5C04RD-UG-S	Direct	IFRH6X04BL-UG	IFRH6X04TL-UG
IFRH5C04TL-UG-S	Direct	IFRH6X04BL-UG	IFRH6X04TL-UG
ISFCH5C04ABU-XG	Direct	ISFCH6X04ABL-UG	ISFCH6X04ATL-UG
ISFCH5C04AGY-XG	Direct	ISFCH6X04ABL-UG	ISFCH6X04ATL-UG
ISFCH5C04ARD-XG	Direct	ISFCH6X04ABL-UG	ISFCH6X04ATL-UG
ISFCH5C04AYL-XG	Direct	ISFCH6X04ABL-UG	ISFCH6X04ATL-UG
IFRH5C02RD-UG-S	Direct	IFRH6X04BL-UG	IFRH6X04TL-UG
IFRH5C02TL-UG-S	Direct	IFRH6X04BL-UG	IFRH6X04TL-UG
IFC6C04BBL-CEG	Direct	ISFCH6X04BBL-UG	ISFCH6X04BTL-UG
IFC6C04BBL-CG-S	Direct	ISFCH6X04BBL-UG	ISFCH6X04BTL-UG
IFRH6C04BL-UG	Direct	IFRH6X04BL-UG	IFRH6X04TL-UG
ISX6X04ABU-LED	Direct	ISX6X04ATL-LED	ISX6X04AYL-LED
ISX6X04AIG-LED	Direct	ISX6X04ATL-LED	ISX6X04AYL-LED
ISX6X04AOR-LED	Direct	ISX6X04ATL-LED	ISX6X04AYL-LED
ISX6X04ARD-LED	Direct	ISX6X04ATL-LED	ISX6X04AYL-LED
IFC6C04BBL-CG-S	Direct	ISFCH6X04BBL-UG	ISFCH6X04BTL-UG
IFRH5C02RD-UG-S	Direct	IFRH6X04BL-UG	IFRH6X04TL-UG
IFRH5C02TL-UG-S	Direct	IFRH6X04BL-UG	IFRH6X04TL-UG
IFRH5C04BL-UG-S	Direct	IFRH6X04BL-UG	IFRH6X04TL-UG
IFRH5C04RD-UG-S	Direct	IFRH6X04BL-UG	IFRH6X04TL-UG
IFRH5C04TL-UG-S	Direct	IFRH6X04BL-UG	IFRH6X04TL-UG
IFL6C04IG-ZGS/N	No Replacement	NO-REPLACEMENT	
IFV6C04BL-ZGS	No Replacement	NO-REPLACEMENT	
IFV6C04IG-ZGS/N	No Replacement	NO-REPLACEMENT	
IURH6X04RD-UG	Direct	IURH6X04BL-UG	IURH6X04TL-UG
ISFCH6X04BBL-US	Direct	ISFCH6X04BBL-UG	ISFCH6X04BTL-UG
ISFCH6X04ATL-XG	Direct	ISFCH6X04ABL-UG	ISFCH6X04ATL-UG