



1 Products affected

Product hierarchy no.				Part no.	SBU	Product Type
SBU	PG	PUG	Type			
01	002	012	0000000538	0031.2500	Circuit Protection	FUP Fuseholder w/o fuse carrier
				0031.2510		FUP Fuseholder 5x20
				0031.2520		FUP Fuseholder 6.3x32

2 Type of change

- Change of material
- Change of product design

3 Detailed description of change

Current plastic material	New plastic material
Thermoset	Thermoplastic
Current product appearance	New product appearance
ISO view	ISO view
	

- New product design
- Position of product marking changed

4 Reason of change

- Replace plastic material thermoset with thermoplastic for a more reliable moulding process
- Change to a modern design

5 Release date

The change takes effect in week 11/2024 (Date code 2411 or higher on label).
Parts on stock will be used upon depletion.

Product Change Notification					PCN FUP Change of material		
owner	creation date	release date	released by	change order	rev	page	D10-078-720
lutzjo	25.09.2023	24.11.2023	schulejo		A	1 of 2	

6 Impact of change and recommended action

- Form No action required. Consider new design at incoming inspection.
- Fit No action required. The combination of sockets and carriers of current and new materials is permissible.
- Function
- Manufacturing
- Label
- Packaging

7 Reference Documents

Kind of document	Document Title
Data Sheet	FUP

Product Change Notification					PCN FUP Change of material		
owner	creation date	release date	released by	change order	rev	page	D10-078-720
lutzjo	25.09.2023	24.11.2023	schulejo		A	2 of 2	