

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M001099A

DATE: 01-Dec-2023

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	PHY1040-01QT-BR	N/A	17-Aug-2024	03-Apr-2025	Part can no longer be manufactured
Discontinuance	PHY1040-01QT-RR	N/A	17-Aug-2024	03-Apr-2025	Part can no longer be manufactured
Discontinuance	PHY1070-01QD-BR	N/A	17-Aug-2024	03-Apr-2025	Part can no longer be manufactured
Discontinuance	PHY1070-01QD-RR	N/A	17-Aug-2024	03-Apr-2025	Part can no longer be manufactured
Discontinuance	PHY1076-01QD-RR	N/A	17-Aug-2024	03-Apr-2025	Part can no longer be manufactured
Discontinuance	PHY1078-01QT-BR	N/A	17-Aug-2024	03-Apr-2025	Part can no longer be manufactured
Discontinuance	PHY1078-01QT-RR	N/A	17-Aug-2024	03-Apr-2025	Part can no longer be manufactured
Discontinuance	PHY1078QT-BR	N/A	17-Aug-2024	03-Apr-2025	Part can no longer be manufactured
Discontinuance	PHY1078QT-RR	N/A	17-Aug-2024	03-Apr-2025	Part can no longer be manufactured
Discontinuance	PHY2078QT-RR	N/A	17-Aug-2024	03-Apr-2025	Part can no longer be manufactured