

Product discontinuation notification (PDN)

Title / short description	Discontinuation of the QTCU item and of some of the QTC* versions
Affected article category	Terminal blocks
Change category	Discontinuation
Change number	IBE230015-00
Reason for PCN/PDN Revision	

Purpose/objective of the change

The QTCU item will be removed from our portfolio. The QTCU items being discontinued can be replaced with existing similar products

Detailed description of the change

Discontinuation due to availability of alternative products

Identifying characteristics

See item list

Start of Production (SOP)	-	Last Time Delivery (LTD)	2025-03-31
Effective date (EOP)	2024-12-31	End of Service (EOSR)	-
End of Sales (EOS)	2024-12-31		

Short-term change (< 6 months) or discontinuation (< 12 months), due to:

- | | | |
|---|---|--|
| ☐ Software / Firmware Bugfix | ☐ Short-term delivery stop by supplier | ☐ Short-term recall by supplier |
| ☐ Force majeure | ☐ Product improvement with customer benefits | |
| ☐ Others | | |

Attachments

- Material_list.csv
- PDN-IBE230015-00_DE
- PDN-IBE230015-00_EN

Material list

Item no.	Item Type	Hardware old	Firmware new	Item no.	Substitute item Type
1150225	QTCU 1,5 L BU			3205020	QTC 1,5 L BU
3050015	QTCU 1,5			3205019	QTC 1,5
3050028	QTCU 1,5 BU			3205022	QTC 1,5 BU
3050031	QTCU 1,5-PE			3205035	QTC 1,5-PE
3050044	QTCU 1,5-TWIN			3205048	QTC 1,5-TWIN
3050057	QTCU 1,5-TWIN BU			3205051	QTC 1,5-TWIN BU
3050060	QTCU 1,5-TWIN-PE			3205064	QTC 1,5-TWIN-PE
3050303	QTCU 2,5-TWIN			3206445	QTC 2,5-TWIN
3050316	QTCU 2,5-TWIN BU			3206461	QTC 2,5-TWIN BU
3050329	QTCU 2,5-TWIN-PE			3206474	QTC 2,5-TWIN-PE
3205118	QTTCB 1,5 RD			3205116	QTTCB 1,5
3205213	QTC 1,5-MT BU			3205103	QTC 1,5-MT
3206254	QTC 1,5 RD			3205019	QTC 1,5
3206267	QTC 1,5 OG			3205019	QTC 1,5
3206283	D-QTCU 1,5				
3206296	D-QTCU 1,5-TWIN				
3206539	QTCU 2,5			3206416	QTC 2,5
3206542	QTCU 2,5 BU			3206429	QTC 2,5 BU
3206555	QTCU 2,5-PE			3206432	QTC 2,5-PE
3206597	D-QTCU 2,5				