



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001101

DATE: 18-Dec-2023

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	806-0637-20+D	N/A	17-Dec-2024	15-Jun-2025	Part can no longer be manufactured
Discontinuance	DS26503LN+GSW	N/A	18-Dec-2023	15-Jun-2024	Part can no longer be manufactured
Discontinuance	DS26504LN+GSW	N/A	18-Dec-2023	15-Jun-2024	Part can no longer be manufactured
Discontinuance	DS26504LN+TGSW	N/A	18-Dec-2023	15-Jun-2024	Part can no longer be manufactured
Discontinuance	DS3150TN+GSW	N/A	18-Dec-2023	15-Jun-2024	Part can no longer be manufactured
Discontinuance	MAX19985AETX+	N/A	17-Dec-2024	15-Jun-2025	Part can no longer be manufactured
Discontinuance	MAX19985AETX+T	N/A	17-Dec-2024	15-Jun-2025	Part can no longer be manufactured
Discontinuance	MAX20361BEWC+	MAX20361CEWC+	17-Dec-2024	15-Jun-2025	Part can no longer be manufactured
Discontinuance	MAX20361BEWC+T	MAX20361CEWC+T	17-Dec-2024	15-Jun-2025	Part can no longer be manufactured
Discontinuance	MAX2044ETP+	N/A	17-Dec-2024	15-Jun-2025	Part can no longer be manufactured
Discontinuance	MAX2044ETP+T	N/A	17-Dec-2024	15-Jun-2025	Part can no longer be manufactured
Discontinuance	MAX22412CASA+	ADUM1252ASA+	18-Dec-2023	15-Jun-2024	The part was not released
Discontinuance	MAX22412CASA+T	ADUM1252ASA+T	18-Dec-2023	15-Jun-2024	The part was not released
Discontinuance	MAX98932EWX+	N/A	17-Dec-2024	15-Jun-2025	Part can no longer be manufactured
Discontinuance	MAX98932EWX+T	N/A	17-Dec-2024	15-Jun-2025	Part can no longer be manufactured
Discontinuance	MAX9988ETP+	N/A	17-Dec-2024	15-Jun-2025	Part can no longer be manufactured
Discontinuance	MAX9988ETP+T	N/A	17-Dec-2024	15-Jun-2025	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 18-Jan-2024